

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

John M. Powell
Frank Jones & C. Stone
January, 1967
C. S. File No. 54/36

John M. Powell
Frank Jones
June, 1967
C.S. File No. 54/44

$\frac{1}{4}$ Corner to Sec. 5, T32-8W. & Sec. 32, T31-8W.
Found - $\frac{5}{8}$ " I.Rod(not $\frac{1}{2}$ " I.Pipe) at $\frac{1}{4}$ Corner. See Ren. #10.
Orig. 52" D. Fir, now down, N. 9° E. 34.3 ft.
Orig. 40", now 54" D.Fir, S. 33° W. 49.5 ft., old axe work visible, snag top.
14" Laurel N. 15° W. 8.1 ft., scribe visible 3642 BT.
New BT: 20" D.Fir S. 9° W. 23.5 ft. mkd. $\frac{1}{4}$ S 5 CS BT.
Note - Call on creek at 39:50 hits very good at corner.
This corner lies west of creek 33.0 ft.

34

Sec. Cor. to Secs. 5 & 6, T32-8W. & Secs. 31 & 32, T31-8W.
Found - No trace of Original Corner, See Ren. #9.
 $\frac{5}{8}$ " I.Rod at Corner (not $\frac{1}{2}$ " I.Pipe)
12", now 13" Tan Oak, S. 10° E. 11.1 ft. mkd. 3642 BT.
6", now 7" Tan Oak, S. 29° W. 28.6 ft., mkd. 3642 BT.
6", now 7" Tan Oak, N. 81 $\frac{1}{2}$ ° W. 21.8 ft. mkd. 3642 BT.
5" Tan Oak, now down N. 59 $\frac{1}{2}$ ° E. 6.3 ft.
New BT's: 8" Tan Oak N. 7° E. 30.3 ft. mkd. T31S R8W S32 CS BT.
20" D. Fir S. 4 $\frac{1}{2}$ ° E. 17.7 ft. mkd. T32S R8W S 5 CS BT.
Note - This corner lies on steep, east slope and about 300 ft. west of Hayes Creek.

35

$\frac{1}{4}$ Corner to Section 6, T32-8W. & Sec. 31, T31-8W.
Found - 1 $\frac{1}{4}$ " Iron Pipe at $\frac{1}{4}$ corner, See Ren. #15, T31-8W.
Found - Orig. 36" Fir, now stob, S. 10° W. 7.9 ft.
30" Fir, now stump, N. 34° W. 23.1 ft., scribe visible.
40", now 42" Fir, S. 58° E. 39.7 ft.
New BT: 8" Tan Oak N. 31 $\frac{1}{2}$ ° W. 64.0 ft. scribed $\frac{1}{4}$ S31 CS BT.
Note - This corner lies 185.0 ft. East of Creek.

36

Feb. 6, 1967

Corner to Sections 7 and 18 only, T32-8W.
Found - 36" D.Fir, now down, N. 80° E. 15.2 ft., scribe visible. #123
30", now 36" D. Fir, S. 82° E. 37.6 ft., shows good scar.
Reset - GLO Brass Cap properly marked in 1917. (B.G. found out of ground)
New BT: 36" D.Fir N. 70 $\frac{1}{2}$ ° E. 57.3 ft. mkd. T32S R8W S7 CS BT.
Note - This corner lies in bottom of deep ravine, approx. 800.0 ft. S. of Jeep Road, location tag on road.

37

Corner to Sections 12 and 13 only, T32-9W.
Found - 12", now 19" D. Fir N. 3 $\frac{1}{2}$ ° W. 126.7 ft., shows good scar.
No trace of SW BT.
GLO Brass Cap at corner, properly marked in 1917.
New BT's: 9" D.Fir S. 62° W. 15.0 ft. mkd. T32S R9W S13 CS BT.
No other good trees closer (NWquad)
Note - This corner lies on top of ridge, approx. 260 ft. N. of Jeep Road.

38

Section Corner to Sections 24 and 25 only, T32-9W.
Found - G.L.O. Brass Cap, properly marked in 1917.
6" Laurel, now dead, S. 82° W. 30.4 ft. scribe visible "9W 25 BT".
24", now 28" D.Fir, N. 71° W. 46.2 ft., shows good scar.
New BT: 5" D. Fir S. 14° W. 5.7 ft. mkd. S25 CS BT.
Note - This corner lies on top of spur running E. & W.

39

Corner to Sections 19 and 30 only, T32-8W.
Found - G.L.O. Brass Cap at Sec. Cor., properly marked in 1917
Orig. 16", now 14" D.Fir, S. 78° E. 10.6 ft., shows good scar.
Orig. 18", now 16" Laurel, N. 13° E. 30.4 ft., tree has dead top, & very faint scribing visible, "T32SR8W S19 BT".
New BT: 9" Yew N. 52° E. 20.2 ft. scribed T32S R8W S19 CS BT.
Note - This corner lies 40 ft. north of ravine.

40