

**Douglas County Surveyor's Record of
Government Corners Renewed**

32 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

Gerald D. Riley
For: Giustina Bros.
June 3, 1987
C.S. 63/61

1/4 Corner for Sections 19 and 20
Set - 5/8" x 20" rebar with cap stamped "Riley 705".
BTs - 8" pine, N.67°E., 6.2 ft. scribed "1/4 BT".
10" Fir, S.12°E., 19.9 ft. scribed "1/4 BT".

117

6/3/87

Max Hull LS 901
For: Gregory For
Products
Oct. 1990
M 111 - 4
C.S. 63/115

Section corner for sec's 24 & 25 T.32 S. R.8 W. & sec's 19 & 30
T.32 S. R.7 W.

118

Set - 5/8" X 30" I.R. with cap mkd. "HULL RS 901"
B.T.s - 8" fir, S.62°W., 7.20 ft.
6" fir, S.54°E., 6.90 ft.
7" madrone N.16°E., 17.90ft.
10" fir, N.04°W., 45.60 ft.

Note - Corner falls on blazed line running west and north/south
blazed line bears east 15 ft.

10/90

Raymond Brown
L.S. #2391
May 23, 1991
C.S. 63/129

1/4 Corner for Sections 6 and 7
Found - 1975 BLM brass cap in good condition
An orig. 6" now 12" D.Fir bears N.28°W., 34.66 ft. with healed
double blaze, in good shape, Added metal tag.
An orig. 54" now 54" D. Fir stump, 3 ft. tall bears S.20°E., 26.73 ft
with partly healed blaze, some scribing visible. Stump too short
and damaged for capping, has metal tag.

Set - At corner, placed 6 ft. tall steel fence post, set 18" into ground,
1 foot southwest of corner.

New BTs - A D.Fir; 4" dia. bears N.57°E., 39.0 ft. mkd. "1/4 S6 BT" with
tag.

A Laurel, 5" dia. bears S.71°E., 35.6 ft. mkd. "1/4 S7 BT"
with tag.

A Tan Oak, 5" dia. bears S.54°W., 11.2 ft. mkd. "1/4 S7 BT"
with tag.

Found existing boundary tree: A Chinquapin, 16" dia. bears S.89°E., 29.9 ft.
dist. has line blaze marks and metal boundary tag.

5/23/91

Randall W. Smith
Deputy, Doug.Co.
Surveyors Office
Ed Monrean
Sept. 24, 1992
C.S. 64/32

Section corner for sec's 4,5,8 & 9
Found - 1975 BLM brass cap on an iron pipe 4" below ground
Orig. SE BT is down, shattered remains of a stump left
Renewal # 15, NE BT is down
All other BT's found as in 1975 BLM Depend. Resurvey & Ren.# 65
New BT - 11" dia. D. Fir double blazed & scribed "T32S R8W S9 CS BT"
bears S.2°E., 56.2 feet

Note - Corner is approx. 50 ft. west of a paved road

FD OK BLM 2002 Resurvey pg 21298

9/24/92

121

Douglas County
Surveyors
Office
Randall Smith
Stephen Flause
Oct. 22, 1992
C.S. File 64/32

Section corner for 29, 30, 31 and 32 (Witness corner)
Found - 1976 2 1/2" DCSO brass cap on a 1 1/2" O.D. Iron pipe protruding
8" above ground. Ren. No. 107

(Unmonumented corner position in slide, is determined at record bearing and
distance (S.37°E., 89.3 ft.) from 1976 BC/IP. A check of brg. and dist.
to 34" dia. D.Fir BT from 1968 is made and checks well with record (S.56 1/2°W.
69.2 ft.) in 1968 visit. The dist. 62.9 ft. in 1976 visit is probably
a transposed number problem. The proper distance of 69.2 ft. appears to
have been used in 1976 corner renewing field work.

Found - 10" now 13" dia. D.Fir with a fully healed double blaze bears
S.2°W., 15.4 ft. (agrees w/rec.) Ren. No. 107

11" Chinquapin now root hole, bears N.2°W., 41.0 ft. (agrees w/rec)

18" now 19" dia. D.Fir with a fully healed double blaze, bears
N.50°E., 7.3 ft. (Rec. N.53°E., 8.0 ft.) BT not typed in
Ren. No. 107, found in field notes of corner renewal in
C.S. 59/18

New BTs - 34" dia. D.Fir with a fully healed double blaze facing Northeast
BT scribed in Ren. No. 90, bears south, 108.8 ft.

11" dia. Madrone bark scribed "WC T32S R8W S30 CS BT" bears
N.17°W., 42.3 ft.

1-21/92

*FD BT & WC
Set BC pg 21101-2*