

Douglas County Surveyor's Record of
Government Corners Renewed

T.32 S. T. S. R.8 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97501

Raymond Brown
May 23, 1991
C.S. 63/129
Cor. Restor. Form

125

South 1/16 Corner between Sections 11 & 12.

Found - BLM brass cap in good condition.
15" Sugar pine now 22", bears N.40°45'E., 72.60 ft. with healed blaze, in good shape. (orig. 1975 tree)
23" D.Fir now 28" dia. stump, 6'6" tall, bears N.87°30'W., 115.30 ft. to center of stump, with healed blaze. (orig. 1975 tree)
Set - At corner, placed 6 ft. tall steel fence post, set 18" into ground, 1 ft. west of corner.
New Accessories -
A Madrona, 8" dia. bears S.54°W., 18.62 ft. mkd. "S1/16 S11 BT"
Found existing fir stump has been debarked, treated with a copper naphthanate solution and will be capped with galvanized metal by 7/01/91.

126

Section Corner for Sections 8,9,16 & 17.

Found - 24" D.Fir corner tree, now 36" stump with old scribes "S & 3" visible.
36" Sugar Pine BT, now a snag, no scribes visible, badly rotted, bears S.60°W., 18.3 ft. (rec. S.65°W., 16.5 ft. must have been to face.
10" Tan Oak BT, face overgrown, bears N.38°E., 43.6 ft. (rec. N.32°E., 41.6 ft.)
18" D.Fir BT, face overgrown, bears N.65½°W., 28.5 ft. (rec. N.69½°W., 31.2 ft.)
34" D.Fir BT, face overgrown, bears S.40°W., 62.0 ft. (rec. S.36°W., 64.0 ft.)
D.C.S.O. Brass Cap, (2½" dia. on a 1" I.P.) bears N.80°E., 3.2 ft. (I added "B.O. 1" to this). SEE RENEWAL # 101 #136
No BT's available in SE Quadrant.
Set - 5/8" x 30" Iron Rod with 1½" aluminum cap marked "Shaner Engineering RLS 430" in center of stump.
Notes - All BT's marked by County surveyor in 1968 were measured to Brass Cap, not center of corner tree.
Corner is 200 yds. easterly of end of old logging road in sec. 8.

127

1/4 Corner for Sections 9 & 16.

Set - By proportional measurement, 2½" Brass Cap on a 1" x 30" Iron pipe, marked "T32S R8W ¼ S9 S16 Rls 430 1994"
New Accessories -
8" D.Fir, bears N.5°W., 15.5 ft. scribed "¼ S9 BT"
10" D.Fir, bears N.30°E., 18.1 ft. scribed "¼ S9 BT"
10" D.Fir, bears S.22°E., 11.1 ft. scribed "¼ S16 BT"
8" D.Fir, bears S.22°W., 13.8 ft. scribed "¼ S16 BT"
6 ft. steel fence post bears West, 1.0 ft.
Note - Corner lies 40 ft. west of top of main ridge which bears N.80°E. and S.80°W.

128

Section Corner for Sections 9, 10, 15 & 16.

Found - 2½" D.C.S.O. Brass cap on a 1" Galv. I.P. SEE RENEWAL # 66.
40" D.Fir BT, scribes visible, bears S.28°W., 34.3 ft.
10" Madrone BT, face overgrown, bears N.53°W., 27.8 ft. (rec. 28.8 ft.)
5" Pine BT, bears East, 33.0 ft. now gone.
New Accessories -
6" D.Fir, bears S.51°E., 11.4 ft. scribed "S15 T32S R8W BT"
Note - Corner lies 500 ft. above & westerly of U.S.

Bruce Shaner
For: Superior Lumber
June 30, 1994
M120 - 31; C.S. 63/154

PG 21095-6

FD OK
BLM 2002
Resurvey

Add
BT B

21093-4

FD OK D. Edwards
8/2005 M148-31