

**Douglas County Surveyor's Record of
Government Corners Renewed**

T.32 S. T.S. R.8W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

129

$\frac{1}{4}$ cor. of sec. 36 & 31 of T32S R7W
 Mon. Fd.- No evidence found. East line of sec. 36 was surveyed and corner was set by proportional measurement.
 Mon. Set- I set a 3" Alum. cap on a 2 $\frac{1}{2}$ "x30" alum. pipe in the ground
 New BT's- 12" D.Fir, scribed " $\frac{1}{4}$ S36 BT", bears N.75°W., 17.8'.
 14" D.Fir, scribed " $\frac{1}{4}$ S36 BT", bears S.47°W., 35'.
 16" D.Fir, scribed " $\frac{1}{4}$ S31 BT", bears S.23°E., 18'.
 16" D.Fir, scribed " $\frac{1}{4}$ S31 BT", bears N.81°E., 43.2'.

130

$\frac{1}{4}$ cor. of sec. 25 & 36
 Mon. Fd.- None
 Bt's Fd.- 18" Laurel (Madrone) BT, original BT, now dead, down & rotten with U.S.B.L.M. bearing tree tag dated sept. 9, 1951 & posted by "Owen" (Note: other BT's posted by Owen in 1951 were found around sec. 36), bears S.20°W., 4.01'.
 16" Madrone, original BT (record Laurel, 10") face rotted & scribes not visible, bears N.70°W., 18.5'. I rescribed on bark " $\frac{1}{4}$ S25 BT".
 Mon. Set- 3" Brass cap on a 2"x30" I.P. in ground.
 New BT's- 32" D.Fir, scribed " $\frac{1}{4}$ S25 BT", bears N.27°E., 26.8'.
 this tree has old cruiser mark "W", I have seen several around sec. 36.
 8" D.Fir BT, scribed " $\frac{1}{4}$ S36 BT", bears S.77°E., 11.3'.
 8" D.Fir BT, scribed " $\frac{1}{4}$ S36 BT", bears S.36°W., 11.8'.
 6' steel fence post, bears S.45°W., 1'.
 corner is west 300' from logging road switchback just to south in sec. 36.

Bruce Shaner
 1/6/96
 M 123 - 17
 C.S. 65/2

Douglas Co. Surveyor's
 Office
 Randall Smith
 Stephen Flause
 Sept. 25, 1996
 C.S. File 65/9-18

131

$\frac{1}{4}$ Corner for Sec. 1; and Sec. 6 of T.32-7
 Found - 2 $\frac{1}{2}$ " dia. brass cap on a 1 $\frac{1}{2}$ " O.D. by 36" long iron pipe is found out of ground. (1965 DCSO) See renewal # 26.
 Accessories Found -
 14" now 24" dia. down D.Fir with a fully healed single blaze, no bark scribing visible, (a portion of lower trunk is covered up). Position of roots agrees well with record "N.70°W., 6.6 ft." O.B.T.
 19" now 20" dia. 8 ft. high D.Fir stump with a fully healed single blaze, bears S.55°E., 6.6 ft. (agrees with rec.) O.B.T.
 Monument Set -
 1965 DCSO BC/IP is set at a position determined from O.B.T's. Brass cap stamping "reset 1996" is added, BC/IP protrudes 6" above ground. A 2 ft. dia. mound of stone is placed around base.
 New Accessories -
 48" dia. 5 ft. high D.Fir stump with an 8" boat spike set in top through BT tag, 1 ft. easterly of center. Boat spike is stamped "B02". Boat spike bears N.80°W., 12.0'
 24" dia. 3 ft. high D.Fir stump with an 8" boat spike set in top, near center through a BT tag. Boat spike is stamped "B01". Boat spike bears N.55 $\frac{1}{2}$ °E., 52.5 ft.
 4 inch "+" is chiseled at toe of northerly face of large rock outcrop, 3 ft. above ground, "+" bears S.58°W., 18.8 ft.
 Note - Corner lies on a steep northwesterly slope. No scribable trees in area around corner. Corner lies approx. approx. N.25°E., 40 ft. from top of large rock outcrop.