

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97801

Section Corner to Secs. 1 and 2 only, T32 - 9W. 7  
 Found - GLO Brass Cap at corner, properly marked in 1917.  
 10", now 13" D. Fir, S. 30° W. 5.3 ft., shows good scar.  
 16", now 18" D. Fir, S. 21° E. 7.9 ft., shows tree opened earlier,  
 scribe visible "T32SR9W S1" Face cut.  
 Reblzd. & Rescrbd: 18" D. Fir S. 21° E. 7.9 ft. mkd. T31S R9W S1 CS BT.  
 Note - This corner lies 10.0 ft. East of very small ravine.

$\frac{1}{4}$  Corner to Section 5 only, T 32 - 9 W. 8  
 Found - GLO Brass Cap at Corner, properly marked in 1917.  
 20", now 21" Laurel, S. 58° E. 11.2 ft., rotted face, " $\frac{1}{4}$ " visible.  
 40", now 42" D. Fir S. 46° W. 21.8 ft., shows good scar.  
 New BT: 10" D. Fir S. 37° E. 15.0 ft. mkd.  $\frac{1}{4}$  S 5 CS BT.

Angle Point (A.P.) T.31S., R.9W. 9  
 This (A.P.) is 4.8 chains East of N $\frac{1}{4}$  corner to Sec. 5, see above.  
 Found - Brass Cap, out of ground, but marked by GLO in 1917.  
 12", now 14" Laurel, S. 17° W. 12.5 ft., tree rotten but  
 found scribe marks. Try to count rings, but too fine.  
 No trace of N.E. BT.  
 Reset - Brass Cap which falls in Skid Road.  
 New BT's: 8" Cedar S. 61° E. 46.4 ft. mkd. A P CS BT.  
 25" Pine S. 25° W. 34.6 ft. mkd. A. P. CS BT.

Sec. Cor. to Sections 32 and 33 only, T 31 - 9 W. 10  
 Found - GLO Brass Cap at corner, properly marked in 1917.  
 Orig. 14" Fir N. 33° E. 15.0 ft., opened for scribe "T", burned  
 face.  
 18", now 20" D. Fir N. 29° W. 33.0 ft., shows scar.  
 New BT: 13" D. Fir N. 42° W. 30.3 ft. mkd. T31S R9W S32 CS BT.  
 Reblzd. & Rescrbd: 14" D. Fir N. 33° E. 15.8 ft. mkd. T31S R9W S33 CS BT.

Corner to Secs. 34 and 35 only, T31-9W. 11  
 Found - GLO Brass Cap at Cor., properly mkd. in 1917.  
 20", now 33" D. Fir, N. 1 $\frac{1}{2}$ ° E. 330.0 ft., shows good scar.  
 36", now 40" D. Fir Snag, N. 5 $\frac{1}{2}$ ° W. 329.4 ft., shows good scar.  
 Note - Did not open these trees, being convinced they are right  
 by surrounding trees which are small & other badly burnt stumps.  
 New BT's: 10" D. Fir N. 40° W. 27.0 ft. mkd. T31S R9W S34 CS BT.  
 10" D. Fir N. 37° E. 32.7 ft. mkd. T31S R9W S35 CS BT.

$\frac{1}{4}$  Corner to Section 35 only, T31-9W. 12  
 Found - GLO Brass Cap, properly mkd. in 1917.  
 18" D. Fir, now down, N. 62° W. 31.7 ft., tree very rotten.  
 8" Maple, now 14", N. 25° E. 27.1 ft., shows good scar.  
 Orig. 36", now 40" D. Fir, S. 60° E. 27.1 ft., scribe visible.  
 New BT: 11" D. Fir N. 80° W. 78.1 ft. mkd. ° S35 CS BT.

A. P. on North Lines, T32S. R9W. 13  
 Note - This A. P. lies 142.8 ft. E. of corner to Sections 3 & 2 only,  
 T.32-9W, which was found in good condition.  
 Found - Corner Tree, now 72" S. Pine Stob, scribe visible,  
 "A P BT on northeast side."  
 Orig. 30", now 37" D. Fir, N. 70° E. 38.3 ft., scribe visible.  
 30" D. Fir, now splintered Stub, S. 74° W. 20.5 ft.  
 Set - Brass Cap on N. Side of S. Pine Stob, mkd.: T 31 S R 9 W  
 County Surveyor's A. P.  
 Office, 1967 T 32 S R 9W  
 New BT: 9" Laurel N. 41° W. 11.0 ft. scribed A. P CS BT.

John M Powell  
 Frank Jones & Joe Brady  
 March and April, 1967  
 C.S. File No. 54/32

RE-RENEWED CORNER NO. #74