

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

21

$\frac{1}{4}$ Corner to Sections 3 and 4.
Found - GLO Brass Cap at $\frac{1}{4}$ Corner properly mkd. in 1917.
18", now 19" D. Fir S. 46° E. 26.4 ft., shows good scar.
20" D. Fir S. 68° W. 30.4 ft., falls in skid road, No trace.
New BT: 46" D. Fir N. 4 $\frac{1}{2}$ ° W. 31.0 ft. mkd. $\frac{1}{4}$ S 4 CS BT.

22

Section Corner to Sections 3 - 4 - 9 - 10.
Found - GLO Brass Cap at Corner properly mkd. in 1917.
20", now 23" D. Fir, N. 61° E. 23.1 ft., shows good scar.
20", now 26" D. Fir, S. 72° W. 36.3 ft., shows good scar.
18", now 22" D. Fir, N. 26° W. 24.4 ft., shows good scar.
14", now 20" Yew, S. 66° W. 39.3 ft. (Record S. 68° W. 38.3').
(faint scribe visible "3 S", face badly rotted)
Reblzd. & Rescrbd.: 20" Yew S. 66° W. 39.3 ft. mkd. T22S R9W S10 CS BT.
Note - This corner lies approx. 200.0 ft. E. of logging road.
Brass Cap is flush with ground. All trees tagged & location tag on road.

23

$\frac{1}{4}$ Corner to Sections 9 and 10.
Found - GLO Brass Cap at Corner, properly mkd. in 1917.
7", now 8" Yew, N. 30° E. 13.2 ft., tree rotted, scribe marks not legible.
12", now 15" Chinquapin, N. 87° W. 17.8 ft., rotten face, "4 S9" visible.
New BT's: 9" Chinquapin N. 62° E. 3.8 ft. mkd. $\frac{1}{4}$ S10 CS BT.
14" Chinquapin S. 31° W. 24.4 ft. mkd. $\frac{1}{4}$ S9 CS BT.

24

$\frac{1}{4}$ Corner to Sections 4 and 9.
Found - GLO Brass Cap at Corner, properly mkd. in 1917.
30", now 39" D. Fir, S. 74° W. (Record S. 77° W.) 57.4 ft., shows good scar.
36" D. Fir, now 47" Stump, N. 40° W. 67.3 ft., shows good scar.
New BT's: 14" D. Fir N. 4° E. 8.2 ft. mkd. $\frac{1}{4}$ S4 CS BT.

25

Section Corner to Section 4 - 5 - 8 - 9.
Found - GLO Brass Cap at Corner, properly mkd. in 1917.
16", now 18" D. Fir, N. 47° E. 10.6 ft., opened for scribe "W".
20", now 23" D. Fir, N. 74° W. 27.1 ft., shows good scar.
40", now 41" D. Fir S. 10° W. 27.1 ft., shows good scar.
S. E. Chinquapin down & rotten.
New BT: 21" D. Fir S. 40° E. 26.6 ft. mkd. T32S R9W S9 CS BT.

26

$\frac{1}{4}$ Corner to Sections 8 and 9.
Found - GLO Brass Cap at Cor., properly mkd. in 1917.
18" D. Fir, now 20" Snag, N. 68° E. 20.5 ft., shows good scar.
30" D. Fir, now stump, N. 70° W. 26.4 ft.
New BT's: 5" Chinq. S. 72° E. 15.4 ft. mkd. $\frac{1}{4}$ S9 CSBT.
19" D. Fir N. 61° W. 102.7 ft. mkd. $\frac{1}{4}$ S8 CS BT.
Note - This cor. lies 250.0 ft. W. of logging road & about 85.0 ft. N. of small ravine in heavily logged area.

27

$\frac{1}{4}$ Corner to Sections 6 and 7.
Found - GLO Brass Cap at $\frac{1}{4}$ cor., properly mkd. in 1917.
5" chinquapin, now 7", N. 20° W. 34.3 ft., rotted.
16" Yew, now 16", down & face rotted, S. 61° W. 15.2 ft., scribe visible.
New BT's: 9" Chinquapin S. 75° W. 31.7 ft. mkd. $\frac{1}{4}$ S 7 CS BT.
12" Pine N. 13° E. 40.1 ft. mkd. $\frac{1}{4}$ S 6 CS BT.
Note - This cor. lies on top of small spur, approx. 275.0' W. & 125.0' North of creek.

John M. Powell
Frank Jones & J. Brady
May, 1967
C.S. File No. 54/44