

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

28

Section Corner to Sections 6 & 7 only, T32-9W.  
Found - G.L.O Brass cap, properly mkd. in 1917  
30", now 40" D. Fir N. 84° E. 22.4 ft., shows good scar.  
48", now 60" D. Fir S. 14° E. 38.9 ft., opened & found scribing.  
New BT: 48" D. Fir S. 76° E. 59.6 ft. mkd. T32S R9W S7 CS BT.  
Note - S. E. Tree is rotting.

29

Section Corner to Sections 14 - 15 - 22 - 23.  
Found - 40", now 46" D. Fir, N. 51° E. 64.7 ft., shows good scar.  
36", now 41" D. Fir, S. 53° W. 24.4 ft., shows good scar.  
24", now 38" D. Fir, N. 43° W. 24.4 ft., shows good scar.  
36" D. Fir, now 40" Snag, S. 47° E. 32.3 ft., shows good scar.  
G.L.O. Brass Cap, 1917, properly marked at corner.  
New BT: 6" D. Fir S. 26° E. 27.1 ft. mkd. T32S R9W S23 CS BT.  
Note - This corner lies approx. 180.0 ft. south of logging road.

30

Section Corner to Sections 13 - 14 - 23 - 24.  
Found - G.L.O. Brass Cap, 1917, properly marked at corner.  
36" D. Fir, now stump, N. 8° E. 83.8 ft., no scar visible.  
36" D. Fir, now stump, S. 78° E. 83.3 ft., scribe visible "9W".  
48" D. Fir, now stump, S. 44½° W. 157.4 ft., shows good scar.  
30", now 37" D. Fir, N. 51° W. 80.5 ft., shows good scar.  
New BT's: 12" D. Fir N. 19° W. 15.0 ft. mkd. T32S R9W S14 CS BT.  
6" D. Fir N. 72° E. 8.0 ft. mkd. T32S R9W S13 CS BT.  
8" D. Fir S. 11° E. 24.7 ft. mkd. T32S R9W S24 CS BT.  
9" D. Fir S. 28° W. 25.5 ft. mkd. T32S R9W S23 CS BT.

31

¼ Corner to Sections 13 and 24.  
Found - G.L.O. Brass cap, 1917, properly marked at ¼ corner.  
16", now 24" D. Fir, S. 25° E. 45.5 ft., shows good face.  
36", now 38" D. Fir Stump, N. 48½° W. 40.9 ft., shows scribing "¼ S13 BT".  
New BT's: 12" D. Fir N. 29° W. 15.6 ft. mkd. ¼ S13 CS BT.  
Note - ¼ Corner lies 90 ft. East of Road.

32

Section Corner to Sections 23 - 24 - 25 - 26.  
Found - G.L.O. Brass Cap, 1917, properly marked at Corner.  
36" Pine, now Snag, N. 5° W. 29.7 ft., scribe visible T32SR9WS23 BT.  
40" D. Fir, now Snag, S. 52° W. 27.7 ft., scribe visible "S26".  
36" D. Fir, now down, N. 32° E. 39.6 ft., shows scar.  
30" D. Fir, now 37", S. 25° E. 59.4 ft., shows good scar.  
New BT's: 36" D. Fir N. 6° E. 32.8 ft. mkd. T32S R9W S24 CS BT.  
41" D. Fir S. 57° W. 34.8 ft. mkd. T32S R9W S26 CS BT.  
6" Chinquapin N. 24° W. 22.5 ft. mkd. T32S R9W S23 CS BT.  
Note - Corner lies 330.0 E. of ridge top & 600.0 ft. south of ridge top.  
June 1, 1967

33

Section Corner to Sections 7 - 8 - 17 - 18.  
Found - G.L.O. Brass Cap, 1917, properly marked at Corner.  
18" Chinquapin, now 18" Snag, N. 57° W. 46.9 ft., shows scribing.  
40" Pine, now 42" Snag, N. 46° E. 25.7 ft., shows scribing.  
40" Fir, now 42", S. 22° E. 48.8 ft., shows good face.  
18" Chinquapin, now down, S. 87° W. 25.7 ft., shows face.  
New BT's: 14" D. Fir N. 80½° W. 67.7 ft. mkd. T32S R9W S7 CS BT.  
6" D. Fir N. 34° E. 28.0 ft. mkd. T32S R9W S8 CS BT.  
14" Chinquapin S. 74° W. 43.3 ft. mkd. T32S R9W S18 CS BT.

34

Section Corner to Sections 5 - 6 - 7 - 8.  
Found - G.L.O. Brass Cap, 1917, properly marked at corner.  
9", now 10" Pine, S. 39° W. 18.5 ft., burnt face, scribe visible,  
"T 32 S" "W" other marks not legible.  
No other BT's. found.  
New BT's: 8" D. Fir S. 63° W. 15.2 ft. mkd. T32S R9W S7 CS BT.  
15" Pine N. 70° W. 20.3 ft. mkd. T32S R9W S6 CS BT.  
15" D. Fir S. 70° E. 14.0 ft. mkd. T32S R9W S8 CS BT.  
5" Chinquapin N. 69½° E. 19.5 ft. mkd. S5 CS BT.  
Note - This corner lies 20.0 ft. south of small ravine.