

Douglas County Surveyor's Record of  
Government Corners Renewed

T 32 S T. S. R9W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

35

Section Corner to Sections 9 - 10 - 15 - 16.  
Found - G.L.O. Brass Cap, 1917, properly marked at corner.  
36", now 40" Fir, N. 14° E. 174.2 ft., shows good scar.  
40", now 48" Fir, S. 44° E. 35.6 ft., shows good scar.  
36", now 46" Fir, S. 7° W. 71.3 ft., shows good scar.  
16", now 27" Fir, N. 48° W. 164.3 ft., shows fair scar.  
New BT's: 7" Chinquapin N. 6° E. 14.3 ft. mkd. T32S R9W S10 CS BT.  
8" D.Fir N. 61° W. 38.6 ft. mkd. T32S R9W S9 CS BT.

36

$\frac{1}{4}$  Corner to Sections 10 and 15.  
Found - GLO Brass Cap, 1917, properly marked for  $\frac{1}{4}$  corner.  
8", now 28" D.Fir, N. 64° E. 33.7 ft., shows a face.  
8" S. Pine, now down, S. 81° W. 37.0 ft., down & rotted.  
Rescribed: 28" D.Fir N. 65° W. 33.7 ft. mkd.  $\frac{1}{4}$  S10 CS BT.  
New BT: 12" D.Fir S. 16° W. 10.7 ft. mkd.  $\frac{1}{4}$  S 15 CS BT.

37

$\frac{1}{4}$  Corner to Sections 3 and 10. (Witness Corner)  
Found - Orig. 48", now 53" Fir, N. 25° E. 13.2 ft., opened for  
scribing, scribe visible.  
No trace of 30" Fir to S.W., in roadway.  
Do not find U.S. G.L.O. Brass Cap as corner lies along  
East edge of Jeep Road.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 9 W  
Office W.C. 10 ft. W. to  
1967  $\frac{1}{4}$   $\frac{S}{S}$   $\frac{3}{10}$   
New BT;s: 7" Chinquapin S. 75° E. 13.6 ft. mkd. W.C.  $\frac{1}{4}$  S10 CS BT.  
7" Pine N. 14° W. 24.2 ft. mkd. W.C.  $\frac{1}{4}$  S 3 CS BT.

38

Section Corner to Sections 10 - 11 - 14 - 15.  
Found - G.L.O. Brass Cap, 1917, properly marked for  $\frac{1}{4}$  corner.  
7", now 11" Chinquapin, N. 30° E. 17.2 ft., shows scribing.  
48", now 68" S. Pine Snag, S. 5° E. 21.8 ft., shows scribing.  
48", now 70" D.Fir, S. 52° W. 87.1 ft., shows good face.  
5", now 8" Laurel, N. 61° W. 35.0 ft., shows good face.  
New BT: 12" D.Fir S. 67° E. 5.2 ft. mkd. T32S R9W S11 CS BT.

US. General Land Office

39

Corner to Sec. 6, T32-9W. & Sec. 1, T32-10W.  
Found - GLO Brass Cap, 1917 mkd. thus: R10W S 1 | S 6 R9W  
T32S  
1917  
Found - 16", now 20" Fir, S. 23° W. 15.7 ft., shows good scar.  
16" Fir, found to be Pine Snag, S. 24° E. 39.6 ft.,  
opened for scribing "R9".  
New BT's: 23" Fir S. 43° E. 37.8 ft. mkd. T32S R9W S6 CS BT.

40

Corner to Sections 12 and 13, T32-10W.  
Found - U.S. GLO Brass Cap, 1917, properly marked at corner.  
Original Corner Stone.  
72" D. Fir, now 72" Snag, S. 50° W. 9.2 ft., opened  
and found scribing.  
24", now 28" Fir, N. 42° W. 7.2 ft., shows scar.  
Rescribed: 28" D.Fir N. 42° W. 7.2 ft. mkd. T32S R10W S12 CS BT.  
New BT: 10" D.Fir S. 85° W. 30.0 ft. mkd. T32S R10W S13 CS BT.  
Note - This corner lies 50 ft. east of creek.

41

Corner to Sections 7 and 18 only, T32-8W.  
Found-36" D.Fir, now down, N. 80° E. 15.2 ft., scribe visible.  
30", now 36" D.Fir, S. 82° E. 37.6 ft., shows good scar. #75  
GLO Brass Cap, out of ground. RESET in proper place.  
New BT: 36" D.Fir N. 70 $\frac{1}{2}$ ° E. 57.3 ft. mkd. T32S R8W S7 CS BT.  
Note - This corner lies in bottom of deep ravine, approx. 800 ft.  
south of jeep road, location tag on road.

John M. Powell  
Frank Jones & J. Brady  
June, 1967  
C.S. File No. 54/44

RE-RENEWED