

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

EAST

65  
 $\frac{1}{4}$  Corner to Section 12 only, T32-9W.  
 Found - G.L.O. Brass Cap properly marked in 1917.  
 36", now 42" D. Fir S. 27° W. (Record S. 77 $\frac{1}{2}$ ° W.) 82.5 ft., shows scar.  
 6", now 10" Laurel, N. 37° W. 52.8 ft., shows good scar.  
 New BT's: 9" Pine S. 22° W. 27.1 ft. mkd.  $\frac{1}{4}$  S 7 CS BT.  
 10" Pine N. 85° W. 18.7 ft. mkd.  $\frac{1}{4}$  S 7 CS BT.

66  
 $\frac{1}{4}$  Corner to Section 6 only, T32-8W.  
 Found-G.L.O. Brass Cap properly marked in 1917.  
 24" D. Fir, now 30" Windfall, S. 62° W. 40.9 ft. This BT. was  
 about 50 ft. down the hill. There was a good stump hole to  
 get the bearing & distance from, shows good scribe.  
 Other BT was gone.  
 New BT's: 12" Hemlock N. 25° E. 50.6 ft. mkd.  $\frac{1}{4}$  S 6 CS BT.  
 10" Hemlock N. 36° E. 30.6 ft. mkd.  $\frac{1}{4}$  S 6 CS BT.  
 Note - This corner was 50.0 ft. east of creek.

67  
 Corner to Sections 6 and 7 only, T32-8W.  
 Found - G.L.O. Brass Cap at Corner properly marked in 1917.  
 18" Cedar, now 12" Snag, N. 5° E. 38.3 ft., shows scribing.  
 10", now 12" D. Fir, S. 69° E. 31.0 ft., shows good scar.  
 New BT" 6" Tan Oak N. 66° E. 2.0 ft. mkd. T32S R8W S6 CS BT.  
 Note - This corner lies 15.0 ft. south of creek.

EAST  
 68  
 $\frac{1}{4}$  Corner to Section 1 only, T32-9W.  
 Found - G.L.O. Brass Cap at  $\frac{1}{4}$  Corner properly marked in 1917.  
 24" Cedar, now 25" Snag, S. 77° W. 22.4 ft., shows good scribe.  
 New BT's: 42" D. Fir S. 64° W. 23.5 ft. mkd.  $\frac{1}{4}$  S 1 CS BT.  
 36" D. Fir N. 82 $\frac{1}{2}$ ° W. 47.5 ft. mkd.  $\frac{1}{4}$  S 1 CS BT.  
 Note - This corner lies 100 ft. west of creek.

69  
 $\frac{1}{4}$  Corner to Sections 1 and 12.  
 Found - 5" Laurel, now down & rotten, N. 48° E. 8.6 ft. (Record N. 69° E.)  
 Found definite scribe marks but not legible.  
 5", now 8" Laurel, S. 12° W. (Record S. 22° W.) 37.6 ft.,  
 face rotted out, high blaze on tree which is typical work.  
 G.L.O. Brass Cap at  $\frac{1}{4}$  corner properly marked in 1917.  
 New BT's: 7" Tan Oak N. 15° W. 6.2 ft. mkd.  $\frac{1}{4}$  S 1 CS BT.  
 6" D. Fir East 28.8 ft. mkd.  $\frac{1}{4}$  S 12 CS BT.  
 Note - This corner lies west of high ridge 103.0 ft.

70  
 Section Corner to Section 2 - 3 - 10 - 11.  
 Found = G.L.O. Brass Cap properly marked in 1917.  
 48", now 52" D. Fir, N. 79° E. 51.5 ft., shows good scribing.  
 40" D. Fir, now 48" Snag, S. 65° E. 58.1 ft., shows good scar.  
 30", now 37" D. Fir, S. 40° W. 58.1 ft., shows good scar.  
 New BT: 6" Laurel S. 45 $\frac{1}{2}$ ° E. 18.7 ft. mkd.  $\frac{1}{4}$  S 11 CS BT.  
 Note - This corner lies on steep south slope.

71  
 $\frac{1}{4}$  Corner to Sections 2 and 3.  
 Found - G.L.O. Brass Cap properly marked in 1917  
 8", now 10" D. Fir, N. 81° E. 16.5 ft., shows good scar.  
 10" D. Fir, now 11" Stob, S. 85° W. 13.9 ft., shows scribing.  
 New BT: 16" D. Fir N. 76° W. 17.8 ft. mkd.  $\frac{1}{4}$  S 3 CS BT.

72  
 $\frac{1}{4}$  Corner to Section 15 and 16.  
 Found - Rod of GLO Brass Cap. Corner is close to campground.  
 30", now 35" D. Fir S. 88° E. 32.3 ft., shows good scar.  
 16", now 24" D. Fir, N. 34° W. 17.8 ft., shows good scar.  
 Set - Brass Cap at  $\frac{1}{4}$  Corner Mkd: County Surveyor's T32S R9W  
 Office, 1967  $\frac{1}{4}$  S 16 | S 15  
 Bearing Trees are tagged and in good condition.  
 Note - This corner lies 70.0 ft. N. of high ridge running E. & W. &  
 approx. 300' N. of Cold Spring Campground Road. Location Tag on S. side of Road.

John M. Powell  
 Frank Jones & Joe Brady  
 July, 1967  
 C. S. File No. 54/44