

Douglas County Surveyor's Record of  
Government Corners Renewed

T 33 T. S. R 5 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

- C O N T -

Gary Langlitz  
K. Cheney  
Douglas Co. Surveyors  
Oct. 8, 1976  
C.S. 9/24

Gary Langlitz, Doug. Co. Surveyors  
K. Cheney  
Oct. 14, 1976  
C.S. 59/24

Set - Marked portion of stone 16"x10"x6" on East side cap. (stone broke in half).  
Set - Brass cap at orig. stones location. Due to discrepancy in the bearing and dists. in the found BT's, calls from ravine (course S.70°W., 100 ft.) a trail (course S.72°W., 7 ft.) and a location marker, a 12" Fir stump 48" high with upper most 2 1/2 ft. cut with axe 8" square, bearing S.11°47'E., 2.6 ft. dist. from corner are used for evidence to show stone at true location.  
New BT's-A 16" D.Fir, bears S.88°E., 29.6 ft. double blazed & scribed "HT 3 920 CS BT"  
A 16" Sugar Pine bears N.62°E., 36.8 ft. double blazed & scribed "HT 3 920 CS BT".

10/18/76

34

Hard Times Lode, Corner #4, Mineral Survey #920 (Sec. 12)  
Found - A 14", now 16" D. Fir, bears N.14°45'E., 29.4 ft. with healed over blaze. We open entire blaze and find nothing but axe marks At approx. 22 yrs. ring count. (Mineral Survey dated 1953)  
An orig. 9" Incense Cedar, now a snag, bears N.85°E., 10.0 ft. Find nothing on unhealed blaze.  
No evidence of 24"x8"x6" Basalt stone.

Set - A 1"x30" I.P. with brass cap mkd: Douglas Co. Surveyor  
T 33 S R 5 W  
M.S. 920 ✓ Cor. #4  
1976

Brass cap set from orig. aforesaid bearing trees.  
New BT's-A 12" D. Fir, bears S.69°E., 9.3 ft. double blazed and scribed "HT 4 920 CS BT"  
A 7" Yewwood bears S.37°W., 7.4 ft. double blazed & scribed "HT 4 920 CS BT"

10/14/76

35

1/4 Corner for Sec. 34 only, of T32-5  
Set - 1 1/2" I.P. with brass cap in mound of stone, cap mkd.  
T 32 S R 5 W  
1/4 S 34  
1977 L.S. 418

From which:  
A 7" D. Fir bears N.68°E., 28.5 ft. mkd. 1/4 S34 BT.  
A 6" Cedar bears S.50°E., 34.5 ft. mkd. 1/4 S34 BT.

8/77

36

1/4 Corner for Section 2 only. (North)  
Found - A 1967 DCSO brass cap properly marked, on a 1" iron pipe firmly set and protruding 1.0 ft. from a rough pile of stone.  
A 1 1/2" I.P. is found set flush with soil on the southeast edge of the brass caps iron pipe. Ren.'s #3 and 20.  
An Orig. 20" Fir, now a decayed 24" x 54" high Fir stump bears due South 49.1 ft. 48.2 ft. to face (Rec. South 48.2 ft.) opened blaze has scribed "S" visible.  
An orig. 20" Fir, now a decayed 29" x 53" high Fir stump bears S.51°E., 43.4 ft., 42.2 ft. to face.) Rec. S.58°E. 42.2 ft.) Upon partially opening a well healed blaze, the scribing "S2 CS" is found. A BLM BT tag on this stump records the bearing from tree to monument as N.52°W.,  
A 8" Madrone, (Rec. Laurel) is still approx 8" diam., Madrone bears S.69°W., 15.6 ft. Tree has partially healed double blaze with scribing "S2 CS" visible.

Set- Because both face measurements from orig. BT's to brass cap and 1 1/2" iron pipe agree with record and bearing to due South BT is found to agree the monument position is accepted as good. More stones are added to rough pile around monument and the brass cap now protrudes 7" above this pile.

New BT's- A 10" D. Fir bears N.74°W., 35.0 ft. scribed "CC 1/4 S2 CS BT" on a double blaze.  
A 10" D. Fir bears N.41 1/2°E., 71.9 ft. scribed "CC 1/4 S2 CS BT" on a double blaze.

New trees and due South OBT stump are tagged with DSCO BT tags. Cap is located 30.0 ft. south of BLM road 31-5-35.1.

7/29/80

Burton W. Holt  
For: Sun Studs, Inc.  
August. 1977  
M 65 - 44

Stephen Flause  
Deputy - Doug.  
Co. Surveyors Off.  
Bill Stewart  
July 29, 1980  
C.S. 61/11