

Douglas County Surveyor's Record of  
Government Corners Renewed

33 T. S. 6 R. W. W. M.

G. J. Wenderoth  
N. E. Richardson  
April 1942  
M 22-50

✓  $\frac{1}{4}$  Cor. on North side of Sec. 5  
" Eye bolt already set in ground.  
Found stump of original B.T. S. 25° E. 6.9 ft. 1

RE-NEWED SEE CORNER NO. 32  
C.S. 14/1

H. L. Eppstein  
J. H. Wolford  
June 12-1929

✓ North Sec. corner of Secs. 4 & 5 A Wagon Skein in place for corner set by J. Elmer Nelson from old stake. 2  
Set new witness trees, 30" Maple S. 7 $\frac{1}{2}$ ° W. 94 lks. 24" Fir S. 75 $\frac{1}{4}$ ° W. 128 lks. 33

✓  $\frac{1}{4}$  corner on North side of Sec. 4  
I set corner from old stake in place. Set 1" x 48" Iron Pipe  
Marked new witness trees, 14" Ash S. 64° W. 98 lks.  
12" Maple N. 81° W. 82 lks. 3

RE-NEWED SEE CORNER NO. 6 C.S. A/1

J. Wendroth  
Dep. Co. Surv.  
May 1946.  
38/221

$\frac{1}{4}$  COR. BET. SEC. 4 & 5  
Found 2" iron pipe at S.E. Cor Cemetery could find no place of B.T. 4  
Marked 20" Fir S 72° 04' W 34.3 ft.  
12" Alder S 42° 05' E 27.0 ft.

SEC. COR. 4-5-8-9- 5  
Find 2 orig. BT both dead. Set 1 $\frac{1}{4}$ " iron pipe. FD OK BY G. NYGREN 3/24 11/8-79  
Mark 20" Cedar S 82° 20' W 16.0 ft.  
29" Cedar S 1° 35' W 51.2 ft.  
14" Cedar S 63° 52' E 35.9 ft.  
30" Cedar N 19° 56' E 89.5 ft.

B. B. Irving  
Jim Byron  
Ray Irving  
Dec. 17, 1953  
File No. 45/232

N.  $\frac{1}{4}$  corner sec. 4. 6  
Found  $\frac{3}{8}$  inch iron pipe. <sup>Rev. #3</sup> Corner identified from  $\frac{3}{8}$  inch iron pipe and old B.T.s  
scribe marks on said trees visible.  
Blazed and scribe 2 trees: SEE CORNER NO. 17  
12 inch maple, S. 21° E., 27.1 feet, mkd.  $\frac{1}{4}$  S CS BT.  
16 inch alder, S. 64° E., 43.0 feet, mkd.  $\frac{1}{4}$  S CS BT.

Richard L. Templin, Jr.  
October, 1954.  
File 41/310.

Section corner to secs. 3, 4, 9, and 10. 7  
Found an old pitch fence corner post common to the intersection of four fences.  
Found rotted stump of original 12" Fir B. T. with chopped face and trace of scribing under five inches of rotted wood said stump bearing S. 52° W., 46 lks. dist.  
Other B. T.s completely gone. (Lake and Hyde 1855)  
Set 1 $\frac{1}{2}$ " Iron Pipe with galvanized cap and Alum. Tag. mkd. "RE3024" on the north side of pitch corner post.  
Scribed the following new bearing trees:  
14" Fir bears S. 55° W., 35.00 feet dist mkd. T33SR6W S9BT.  
14" Madrone bears N. 82° W., 46.3 feet dist. mkd T33SR6W S4BT.  
10" Yellow Pine bears S. 17° W., 44.2 feet distant mkd T33SR6W S9BT.  
Set BLM Bearing tree tags on madrone and Yellow Pine BT's. FD. O.K. - OCT. 1967 C.S. 54/53

H. W. Lawrence  
March 24, 1955.  
C. S. File No. 41/355

$\frac{1}{4}$  sec. corner to secs. 2 and 11. 8  
Corner set by proportionate measurement. SEE ALSO # 9  
Set a  $\frac{1}{2}$  inch iron rod 36 inches long driven 30 inches into ground, from which:  
A B. Oak, 10 inches dia., bears N. 34° 20' W., 69 feet, marked  $\frac{1}{4}$  S. 2 B. T. 1543.  
A B. Oak, 17 inches dia., bears S. 21° 13' E., 40 feet dist., marked  $\frac{1}{4}$  S. 11 B. T. 1543.

Geo. J. Wenderoth  
C. S. File No. 47/7.  
August, 1955.

$\frac{1}{4}$  corner to secs. 2 and 11. 9  
I drive a  $\frac{3}{8}$  inch pipe over a  $\frac{3}{8}$  inch iron rod. SEE ALSO # 8

FD. OK 7/5/88  
M. 107-16 +  
05 03/62