

Douglas County Surveyor's Record of
Government Corners Renewed

33 T. S. 6 R. W. W. M.

North corner to sections 1 and 2. (Only). 10,
Drive a 1 inch Iron Pipe and scribe two trees:
A 14" Maple, S.10°50'W., 57.0 feet.
A 14" Fir, N.83°20'E., 78.8 feet.
Run west 201.4 feet and renew corner to secs. 35 & 36, T 32 S, R 6 W., from
both O. B. Ts. (See renewal under T 32 S, R 6 W.)

RE-RENEWED CORNER NO. #58
FOUND OK - OCT. 1967

Geo. Wenderoth
August, 1955.
C. S. File # 477

Section Corner common to Sections 1 and 6. (Twp. cor. of T.33W. Rs.6 & 7W.) 11,
Found - Orig. BT., a 12" Ash S.70°W., 35 lks. with obliterated face.
Other trees gone.
Corner falls in Cow Creek.
Set 1 inch iron pipe 35.5 ft. South of true corner as Witness
Corner marked with aluminum tag stamped "RE3024", from which
pipe the following trees bear:
18" Fir bears N.36°W., 23.5 ft. mkd. "S1WCRE3024BT"
24" Fir bears S.67½°E., 57.5 ft. mkd. "S6WCRE3024BT"

Richard L. Templin, Jr.
For Superior Lumber Co. of
Glendale.
March 11, 1958
C. S. File No. 42/344

North Quarter Corner of Section 6 only. 12
Found - 3 inch wood stake scribed "¼ S 6" on South Side.
Original BT. with scribing visible; S 59°W., 117 lks. 24
Scribed a 14" Fir N.48°W. 4.5 ft. mkd. "S6RE3024BT".

Corner Common to Sections 5 & 6 only. 13
Found - Corner in poor condition from which:
Orig. 8" Laurel, S.46°W., 63 lks, now missing.
Orig. 13" Fir S.68°E., 78 lks, now a rotten stump.
Set the corner from the Fir, using compass & chain.
Drove a 1" iron rod & scribed a 12" Fir S.23° 30'E. 38.8 ft.
S5 RS 424 BT. and
42" Fir S.51°W. 62.8 ft. S6 RS 424 BT.

FD 9/8
R. Thompson
RM 3-61
FD OK 8/90
M112-14

Wallace Owen
Robert Dollar Co.
Glendale, Ore.
April 18, 1958
C.S. File No. 42/354

Section Corner to Sections 9, 10, 15 and 16. 14
Found - Original 2 x 2 Post
30" Fir N.15°E. 21 ft. by Kupilles, 1957, I scribed "S-10".
10" Fir S.32°E. 12 ft. Orig. BT scribes illegible.
24" Fir S.86°W. 12 ft. Kupilles, 1957
6" Orig. Fir Stump N.53°W. 22 ft.
Set - New 1" Iron Pipe beside Post

RE-RENEWED CORNER NO. 38

Donald R. Martin
For Herbert Lumber Co.
Mt. E.N.White, Jr.
Mt Hammerley
July 1960 C.S. 51/118

¼ Section Corner to Sections 10 and 15. 15
No Original BT's.
Found - Original 2 x 2 Post
I scribed 15" B. O. S. 4°E. 42 feet.

← NOT IN DOUGLAS COUNTY

¼ Corner to Sections 1 and 2. 16
Original ¼ Corner not found.
Corner set at proportionate distances:
Set - 2" I. Pipe & Scribed:
30" D. Fir S.68°30'W. 30.6 feet.
10" Madrone N.61°00'E. 13.0 feet.
March 1962

RE-RENEWED CORNER NO. #60

By Robert
M. Thompson
For:
Glendale Stud
C.S. 51/171

Corner Common to Sections 31 & 32, T32S R6W.
(South boundary of T32-6W)
Found - Corner in poor condition.
Orig. BT's. were a 24" Laurel, N.15°E., 7 lks., now missing,
and an 8" Laurel N.20°W., 30 links, now a rotten stub.
Set - The corner from the 8" Laurel using compass and chain.
Drove a 7/8" rod and scribed a 6" Laurel, N.26°30'W., 18.1 ft.,
S.31 RS 424 BT, and a 5" Laurel N.28°30'E., 32.3 ft., S32 RS 424 BT.

16-A
SEE #143 IN T.32-6
SEE #62 T33-6

FD BT's
R. Thompson
RM 3-61

RE-RENEWED CORNER NO.

April 18, 1958

Wallace Owen
For Robert Dollar Co.
C.S. File 42/354