

Douglas County Surveyor's Record of

Government Corners Renewed

T. 33 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

FD OK BY G. NVGREEN  
3/94 M118-79

29

Robert M.  
Thompson  
for: Superior  
Logging  
C. S. File  
No. 55/27

East 1/16 Corner to Sections 6 and 7.  
Found - Brass Cap on 2" G.I. Pipe as set in U.S. B,L.M.  
1964 Survey and 1 BT. with scribe visible:  
10" D. Fir, N. 14° W. 20.8 ft. (Record 21.1 ft.) The  
S.W. BT. has been obliterated by road construction.  
New BT: 18" D. Fir S. 61° E. 95.9 ft. scribed "3683 1/16 S7 BT".  
Note - This corner lies just off the northerly edge of a newly  
constructed, forest road switchback, running N - W & S.

Feb. 22, 1967

Section Corner to Sections 32 and 33 only, T32-6W.  
Found - 2" Iron Pipe not found, had been taken, See Ren. #13, T32-6W.  
8", now 14" Apple, N. 81° E. 39.6 ft., scribe visible "BT".  
No trace of other Apple Tree.

30

Set - Brass Cap at Cor. Mkd: County Surveyor's Office  
1967 T 32 S R 6 W S 32 | S 33 S 5

New Bearing Obj.: PK Nail in base of power pole #E2448, S. 87 1/2° W. 75.6 ft.  
PK Nail in base of power pole #2422 S. 87° E. 43.0 ft.  
Note - This corner lies on north edge of road, approx. 175 ft. west of  
Third Street. Corner confirmed by C. R. Birchfield.

RE-RENEWED SECTION CORNER NO. #52

1/4 Corner to Section 32 only, T32-6W.  
Found - 6", now 8" D. Fir, N. 70° E. 10.2 ft., shows good scar.  
28" D. Fir, now stump, N. 24° W. 31.8 ft., faint bark scribe, "BT".  
1/2" I. Pipe at 1/4 cor., see Ren. #29, T32-6W.  
New BT: 10" D. Fir N. 84° W. 36.2 ft. mkd. "1/4 S32 CS BT".  
Note - This corner lies 198 ft. west of 1/4 cor. tod sec. 5 only, see below.

FD OK 8/90  
M112-14

31

1/4 Corner to Section 5 only, T33-6W.  
Found - 1/2" Eye Bolt at 1/4 corner, See Ren. #1, T33-6W.  
Orig. 18" Fir, now stump with rotten face, S. 25° E. 6.6 ft.  
New BT's: 10" D. Fir S. 27° E. 13.2 ft. mkd. 1/4 S 5 CS BT.  
14" D. Fir S. 52° W. 14.3 ft. mkd. 1/4 S 5 CS BT.  
Note - This corner lies 198.0 ft. east of 1/4 cor. Sec. 32 only, Rens. #31.

FD OK 8/90  
R. THOMPSON  
EM 3-61

32

Section Corner to Sections 5 and 4 only, T33-6W.  
Found - Wagon Skein at Section Corner, See Ren. #2, T33-6W.  
30", now 39" Maple, S. 7 1/2° W. 62.0 ft., shows scar.  
No trace of S. W. Tree, falls in street.  
New BT: 14" Maple S. 83° W. 51.2 ft. mkd. T33S R6W S 5 CS BT.  
Note - This corner lies 198.0 ft. east of corner to secs. 32 & 33 only,  
Ren. #302, approx. 25 ft. east of Third Street.

FD OK PER LANE  
M110-6 2-90

33

MICROFILM TO HERE 10/67 -  
Section Corner to Sections 35 and 36 only, T32-6W.  
Found - 1" Iron Pipe at Section Corner, See Ren. #44, T32-6W. #57  
18" D. Fir, now snag, N. 60 1/2° E. 65.8 ft., scribe visible "S BT".  
24", now 25" D. Fir, N. 34° W. 33.9 ft., shows good scar.  
New BT: 18" D. Fir N. 84° E. 34.3 ft. mkd. T32S R6WS36 CS BT.  
Note - This corner lies on north slope about 20 ft. above old skid road.  
Also 201.4 ft. west of C.C. of Sections 2 & 1, T33-6W, found O.K.

Section Corner to Sections 8 - 9 - 16 - 17.  
Found - Orig. 15" W.Oak, now rotten stump, down, S. 43° E. 64.0 ft., reverse  
scribe found "S 3" and other marks.  
Orig. 50" D. Fir, now down burnt, S. 60° W. 72.6 ft., scribe found "BT".  
Orrig. 24" W.Oak, burnt out, N. 55° E. 81.8 ft. (Record N. 50° E.),  
no scribing.  
Orig. 40" Fir, now hole, N. 15° W. 17.2 ft.

35

It seems all dist. are sloped & by using 3 bearings & 4 slope distances,  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office  
1967 T 33 S R 6 W S 8 | S 9 S 17 | S 16

New BT's:

(continued over)

John M. Powell  
Frank Jones & Joe Brady  
Sept. & Oct., 1967  
C. S. File No. 54/53