



NORTH

SECTION 35
T. 28 S.

Old Cor. P.L.C. 54

New Cor.

N 88° 56' E 560.6'

N 88° 55' E 1864.2'

INTERIOR 1/2 COR.
P.L.C. No. 54

N 57° 25' E 596.8'

N 57° 40' E 537.5'

N 68° 28' E 434.3'

N 83° 21' E 378.0'

N 77° 32' E 271.3'

S 70° 43' E 279.8'

S 31° 22' E
128.3'

99.0'

15.64 ACRES

SOUTH
UMPQUA RIVER

MAP SHOWING PROPERTY OF

S. E. MOORE

SEC. 35 T.28 S. R.6 W. W.M.

Surveyed by W.H. Wood
Deputy Co. Surveyor.

OFFICE OF
H.L. EPPSTEIN COUNTY SURVEYOR.
NOV. 16 1925
SCALE 1" =
SURVEY No. 3-21

S. E. Mtn.

St. H. Mtn.	2 1/2 Days	25 ⁰⁰
Car 2 trips	40 M.	4 ⁰⁰
Crean	2 Days	8 ⁰⁰
Recording		2 ⁵⁰
Map Office		

3-21

Reestablish corner to D. L. C. 54
at angle in south line.

From the S.W. Cor which is also
the $\frac{1}{4}$ cor to Secs 34+35 I run
 $N 98^{\circ} 58' E$ 42.80 on line to the $\frac{1}{4}$ cor
to Secs 35+36 which is the record
distance I then measure South 70 ch
but find no evidence of cor or BT's

I therefore establish corner as already located

set I.P. 1 in x 2 ft

(N.W. COR Home Place

S 42° 00' W 55 L

On apple tree 6" diam

N 15° W 50 ch - C.L. 54 - C.S.

CS 3/21

Crown 8 and 11/25 FOR S E MOORE

WOOD - CUM - S. E. MOORE

Solar 2 P.M. Nov. 12/25

the crown br = 17-38-01

24 10.33 14. x 40.85 = 7-02.4

17-45-03.4

2 00

Ref

Set off

17°-43'-03.4

CS 2/21

Reestablish - the $\frac{1}{4}$ cor to sec 34-35

Twp 28 S R 6 W which was not in
place and renew, from B.T. (only
one given) by placing a W stake

Stake scribed $\frac{1}{4}$ - 34-35 C.S.

a { $\frac{1}{2}$ B. Oak 10" Bense S 18° W 73 L
Bend " 10" " South 10 L and is

Scribed $\frac{1}{4}$ sec

Is also S.W. cor to D, L.C. 54

Reestablish The $\frac{1}{4}$ cor to sec 35-36

find B.T. 2 1 down and other
rotting but can be identified

Set $\frac{1}{2}$ B. Oak 12" Bense Scribed

$\frac{1}{4}$ - 35-36 C.S.

from which a B. Oak 12" Bense

11 40° 15' W 89 L Scribed B.T. S, 35 C.S.

a B Oak 12" Bense N 54° 45' E 82 L

Scribed B.T. S, 36 C.S.

C.S. File No. 2/21 J. E. Moore - Sec. 35 T 28 S R 6 W- Surv. W. H. Woods
Map in Vol. 3 pg. 228 5 M 5-77



"TUFTEAR"

FOLDER

TO RE-ORDER SPECIFY

No. 22 1/2 FOLDER

MADE IN U.S.A.

CS FILE FOLDER

CONTAINS

MORE

INFORMATION