

Roseburg, Oregon
Box 90, Melrose Rt.
March 21, 1949

County Engineer
Roseburg
Oregon

Dear Sir:

I have done some surveying in sections 26 and 36, T 23 S,
R 7 W..

I found the following bearing trees at each of these corners
and reset and marked the corner stakes.

S. W. Corner Sec. 36

A 16" Fir snag found with scribe visible
A 31" W. Fir with old BT sears
Set a 4" x 4' cedar stake for corner

1/4 Cor. for 35 and 36

Both BTs found
A 28" Fir Scribe markings burned off
A Ced. windfall with scribe visible
Set 3"x4' fir limb for corner stake

Cor for 26, 27, ²⁶34, and 35 ?

A Fir BT (now 36") S55 degrees E 39 LKS.
An 18" windfall fir with old marks
Rest destroyed by old fire
Set a 4"x4' cedar stake for the corner

1/4 Cor 25 & 36

Both BTs found
The Fir - South 6 LKS has 1/4s inscribed on bark
The Fir - N20E - for 36 LKS is a windfall. The scribe found.
Set a 3"x4' fir stake for 1/4 cor.

South 1/4 cor. for Sec. 36

Found a Fir B.T. marked 1/4 S BT on the bark
Set a 3"x3 1/2' cedar stake for 1/4 cor.

Corner 26, 27, 34 & 35

Found the cedar BT scribe visible
Set a 3"x4' yew post for corner

1/4 Corner for 35 & 26

Found both Fir BTs
Set 3"x4' fir stake for corner

CS 40/190

1/4 Corner 25 & 26

Found both BTs
A maple with grown over face
A dogwood marked 1/4 S.
Set 3"x4' white fir stake

1/4 corner for 23 and 26

Found the 20" Fir and found the scribe
Set 2"x2' Hazel stake for 1/4 corner

Corner for 23, 24, 25, and 26

Two standing Fir BTs found, one with scribe visible
The large 48 Fir BT is now a windfall
A 2"x4' stake set for section corner

Yours very truly,

Claude Kerr

CLAUDE KERR

