

CLAUDE KERR

Real Estate

Timber and Timberlands
ROSEBURG, OREGON
MELROSE ROUTE, BOX 88-M
PHONE 76-J-3

REGISTERED
PROFESSIONAL
ENGINEER

TIMBER CRUISING
AND
LOGGING ENGINEERING

NEW ADDRESS
2430 FOOTHILL DRIVE

June 6, 1950

Douglas County Engineer
Roseburg
Oregon

Dear Sir:

I am sending you information on corners found or reset, or established by myself recently,

In T29S, R3W

Set the 1/4 cor. for Sections 1 and 12 at halfway point between the section corners. Set a 4" x 4' cedar post marked 1/4 S on E & W sides, S 12 on South side, and S 1 on North side (Neither of two original BTs were found.)

I marked two BTs which bear

Red Fir 30", bears N 45° E for 9 Lks.
Red Fir 30", bears S 50° W for 31 Lks.

All corners and Bts found along east boundary Section 12, T29S, R3W,
1/4 Cor. for 12 & 13.

Found iron markings, but markings nearly all gone.

I reset corner from the original BT. Set a 4" x 4' cedar post at corner, and remarked the original BT with 1/4 S BT.

(Original remarked) Laurel 10" N 35° E 16 Lks.
Marked a new BT (Fir 12', bears N 50° E for 18 Lks marked 1/4 BT
Marked a new BT (Laurel 10", bears S 30° E for 9 Lks, marked 1/4 BT.

(Continued on next page)

Received 6/10/50
via Fred
Recorded 6/14/50

FILE 252 DRAWER 40