

1/4 CORNER BETWEEN SECTIONS 1 & 12
T. 25 S., R. 7 W., W. M.

FOUND B.T. FOR SECTION 1. TREE DOWN
BUT SCRIBE MARKS "1/4 S 1 B.T." VISIBLE.
RESET 1/4 CORNER ACCORDING TO
RECORDS, TURNED BEARING TO
OTHER B.T. WHICH IS NOW A STUB,
NO BARK. CORNER IS 3/4" IRON PIPE
FROM WHICH BEARS

A 10" HEMLOCK S12°E 9.3' NEW B.T.
MARKED "1/4 S 12 T 25 S R 7 W B.T."
PLACED TAG ON THIS TREE

A 12" HEMLOCK N53°W 30.1' NEW B.T.
MARKED "1/4 S 1 T 25 S R 7 W B.T."

6-14-55

R. H. GEE

R. J. HENRIKSON

S. DANCHOK

AT A POINT 276' SOUTH ON
THE CENTER LINE OF SECTIONS 12
I GO N78°E 10.0' TO A 48" FIR
WHICH HAS SEVERAL CRUISE
MARKS AND "1/4 S" CARVED WITH
KNIFE IN BARK. THERE IS NO
RECORD OF THIS TREE IN THE

C. S. File No. 42/24-1

COUNTY RECORDS. THIS TREE
WAS NOT DESTROYED.

D. W. Geo

C. S. File No. 42/24