

DESTROYED - BYRON 511-58 - FHE 49/76
SECTION CORNER TO SECTIONS
1, 2, 11 & 12 T255 R7W W1

FOUND SCRIBED 4" x 4" x 3'-0" POST
WHICH WAS BADLY BURNED.
REPLACED POST WITH 3/4" IRON
PIPE FROM WHICH BEARS

A RED CEDAR 40" N30°E 85.8' O.B.T.
SCRIBE MARKS VISIBLE

A RED CEDAR 38" N34°W 21.8' O.B.T.
SCRIBE MARKS VISIBLE

A FIR 50" S53°E 47.5' O.B.T.
SCRIBE MARKS VISIBLE

A RED CEDAR 10" S63°W 55.0' NEW B.T.
MARKED "511 T255 R7W BT"

JUNE 14, 1955

R. H. GEE

R. J. HENRIKSON

S. DANCHOK



C. S. File No. 42/24-2