

Route 2, Box 688A,  
Grants Pass, Oregon.

May 15, 1956

Mr. Ben B. Irving,  
County Surveyor,  
Douglas County,  
Roseburg, Oregon.

Dear Mr. Irving:

The  $\frac{1}{4}$  sec. cor. of secs. 16 and 21, T. 32 S.,  
R. 7 W., W. M., Oregon, was rehabilitated by me at the request  
of Dollar and Patterson Co., Inc. of Glendale, Oregon. The  
detailed description of rehabilitated corner is as follows:

The point for  $\frac{1}{4}$  sec. cor. of secs. 16 and 21, T. 32 S., R. 7 W.,  
W. M., Oregon is determined at the record bearing and distance  
from each of the original bearing trees both of which will be  
destroyed during construction of logging roads.

At the corner point,

Set an iron pipe, 3 ft. long,  $1\frac{1}{2}$  ins. diam., 28 ins. in the  
ground, mkd. RS33; from which new bearing trees:

A Douglas fir, 10 ins. diam., bears S.73°E., 98 lks.  
dist., mkd.  $\frac{1}{4}$  S21 RS33 BT.

A Douglas fir, 10 ins. diam., bears N.77°W., 184 lks.  
dist., mkd.  $\frac{1}{4}$  S16 RS33 BT.



FILED  
RECEIVED

MAY 22 1956

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 42/193-2