

T. 24S., R. 2W.

Remonumentation of $\frac{1}{4}$ S 14 & 23

After logging in section 14, both original bearing trees were in good condition.

At the true point of the corner, I drove a $1\frac{1}{2}$ " iron pipe 24" long, 16" in the ground.

Sept. 13, 1957



FILED
RECEIVED

OCT 8 1957

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 42/306³