

T. 24S., R. 2W.

Renewal of $\frac{1}{4}$ S 27 & 28

Before logging both bearing trees were standing. The B. T. for sec. 27 was a dead snag.

After logging in section 27, the B. T. for that section is a broken stump with scribing visible. The original B. T. for section 28 is in good condition, (now 9" diam.).

At the true point of the corner I drove a $1\frac{1}{2}$ " iron pipe 30" long 18" in the ground, from which;

A fir 38" in diam. bears N. 76° E. 31.6 ft.

marked $\frac{1}{4}$ S 27 253 B. T.

A fir 22" in diam. bears S. 73° W. 14.5 ft.

marked $\frac{1}{4}$ S 28 253 B. T.

Sept. 17, 1957



FILED
RECEIVED

OCT 10 1957

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 42/306-1