

T. 24S., R. 2W.

Sec. 28 - S. E. $\frac{1}{4}$ / S. E. $\frac{1}{4}$

At the E. 1/16 S 28 & 33, the bearing trees marked in my survey of 1953 are in good condition. At the true point of the corner I drove a 1 $\frac{1}{2}$ " iron pipe 30" long 18" in the ground.

At the S. E. 1/16 S 28, the bearing trees marked in my survey of 1953 are in good condition. At the true point of the corner I drove a 1 $\frac{1}{2}$ " iron pipe 30" long 18" in the ground.

At the S. 1/16 S 27 & 28, the bearing trees marked in my survey of 1953 are in good condition. At the true point of the corner I drove a 1 $\frac{1}{2}$ " iron pipe 36" long 24" in the ground.

Sept. 17, 1957



FILED
RECEIVED

OCT 10 1957

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 42/306-8