

T. 25S., R. 2W.

Renewal of $\frac{1}{4}$ S 13 & 14

Before logging in section 13 I could not find the original marked corner stone. Both bearing trees were standing, the one for section 13 in good condition, the one for section 14 a dead snag with scribing visible.

After logging, the same condition exists. At the true point of the corner I drove a $1\frac{1}{2}$ " iron pipe 36" long 20" in the ground, from which;

A hemlock 24" in diam. bears N. 28°W. 26.6 ft.

marked $\frac{1}{4}$ S 14 253 B. T.

Sept. 20, 1957



FILED
RECEIVED

OCT 10 1957

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

600440

C. S. File No. 42/308-10