

T. 25S., R. 2W.

Renewal of S 1/16 S 23 & 24

After logging in the S. E.  $\frac{1}{4}$  of section 23 and the S. W.  $\frac{1}{4}$  of the S. W.  $\frac{1}{4}$  of section 24 I found both bearing trees established in my survey of 1955 dead. The B. T. for section 23 was standing and scribing was visible. At the true point of the corner I drove a  $1\frac{1}{2}$ " iron pipe 36" long 18" in the ground, from which;

A hemlock 10" in diam. bears N.  $26^{\circ}$ E. 55.8 ft.

marked S 1/16 S 24 253 B. T.

A fir 62" in diam. bears N.  $4^{\circ}$ W. 15.3 ft.

marked S 1/16 S 23 253 B. T.

Sept. 20, 1957



FILED  
RECEIVED

OCT 10 1957

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

600 320

C. S. File No. 42/308-14