

THE ROBERT DOLLAR CO.

COW CREEK DIVISION
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

April 18, 1958

Douglas County Surveyor
Douglas County Courthouse
Roseburg, Oregon

Dear Sir:

Found the corner on the township line for the north boundary of Township 33 South, Range 6 West, common to Sections 5 and 6 in poor condition. The original bearing trees were an 8 inch Laurel, S 46 W, 63 links, now missing, and a 13 inch Fir, bearing S 68 E, 78 links, now a rotten stump.

Set the corner from the Fir, using compass and chain. Drove a 1" iron rod and scribed a 12" Fir, S23° 30' E, 38.8 feet S5 RS 424 BT, and a 42" Fir S51° W 62.8 feet S6 RS 424 BT.

Found the corner on the township line for the south boundary of Township 32 South, Range 6 West, common to Sections 31 and 32 in similar condition. The original bearing trees were a 24" Laurel, N 15 E, 7 links, now missing, and an 8" Laurel N 20 W, 30 links, now a rotten stub.

Set the corner from the 8" Laurel using compass and chain. Drove a 7/8 inch rod and scribed a 6 1/4" Laurel, N 26° 30' W, 18.1 feet, S31 RS 424 BT, and a 5" Laurel N 28° 30' E, 32.3 feet, S32 RS 424 BT.

Magnetic declination for all bearings was 19° 30' East.

Yours very truly,

THE ROBERT DOLLAR CO.

Wallace Owen

Wallace Owen
Assistant Engineer

FILED

RECEIVED *WO/jvd*

APR 23 1958

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 42/354

*Rev #64A
T32-6
#13
Rev
T33-6*

*Rev #16A
T35-6*