

RICHARD L. TEMPLIN, JR.  
CONSULTING ENGINEER AND FORESTER  
1004 N.W. HAWTHORNE  
GRANTS PASS, OREGON  
July 20, 1958

County Surveyor  
Douglas County  
Douglas County Court House  
Roseburg, Oregon

Dear Sir:

While doing timber cruising in Section 6, T. 32 S., R. 4 W.,  
W. M., I rehabilitated the following corners:

Township corner common to Townships: T. 31 S., R. 4 W.;  
T. 31 S., R. 5 W.; T. 32 S., R. 5 W.; and T. 32 S., R. 4  
W., W. M.

Found:

- 3/4 in. iron pipe (unmarked)
- 24" Fir S 62 3/4\* W 39.5 ft.  
blaze healed
- 50" Fir stump S 74 1/2\* E 25.5 ft.  
scribing visible
- 40" Fir stump N 65\* E 20.0 ft.  
blaze healed
- 16" Fir stump N 16\* W 54.0 ft.  
blaze healed
- 10" Fir N 79 3/4\* E 9.8 ft.  
scribing visible

Scribed:

- 6" Cedar N 27\* W 16.6 ft.  
mkd. S36 RE3024 BT

1/4 section corner common to Secs. 6, T. 32 S., R. 4 W.,  
and Sec. 1, T. 32 S., R. 5 W., W.M.

Found:

- 12" Fir N 54\* W 52 lks.  
scribing visible

Set:

- 3/4" iron pipe mkd. RE3024

Scribed:

- 22" Fir S 15 1/2\* W 44.0 ft.  
mkd. 1/2 S1 RE3024 BT

FILED  
RECEIVED

SEP 18 1958

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Respectfully,



C. S. File No. 22302

RICHARD L. TEMPLIN, JR.  
CONSULTING ENGINEER AND FORESTER  
1004 N.W. HAWTHORNE  
GRANTS PASS, OREGON

September 15, 1958

Mr. Fred Darby  
County Surveyor  
Douglas County  
Roseburg, Oregon

Dear Sir:

Enclosed find rehabilitation field notes for three government corners in your county.

Most of the work which I have performed in Douglas County during the past two years has been timber cruising, and when a corner is found and needs to be perpetuated, is often monumented and placed on record with your office. However, an aluminum location poster tag is often placed at corners which we feel are true approximate locations and which are marked approximate and how they were placed either by cruising or by survey, if said corners are in fair shape.

In the case of the Township corner of Twps. 32 S. Rgs. 5 & 6 W. : I was requested to cruise the S $\frac{1}{2}$  of S $\frac{1}{2}$  of Section 36, T. 32 S., R. 6 W. for Sunny Valley Logging Co., Grants Pass. After diligent search for this corner, we found remnants of scribing on one of the original bearing trees: I had a crew go in the next day to finish the cruise as I had to be on another job, and they set an iron pipe and scribed new bearing trees before cruising. Sometime during the next two days, the field notes and other information was lost by the chief of party. I had hoped to get back and remeasure the distances and courses to the new bearing trees when I was in that vicinity but to date have not had occasion to do such. Normally we do not perform such work on cruising job, but this corner was so far gone and I knew that there would probably be relogging operations next to it, and all of the fragmentary evidence would be gone. I regret that I have not secured information needed to place the corner on record.

Respectfully,

*R. L. Templin, Jr.*  
R. L. Templin, Jr.

FILED  
RECEIVED

SEP 17 1958

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.