

THE ROBERT DOLLAR CO.

COW CREEK DIVISION
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

September 25, 1959

Douglas County Surveyor
County Courthouse
Roseburg, Oregon

Dear Sir:

The $\frac{1}{4}$ corner common to Section 22 and 27, T 31 S, R 9 W, was found in poor condition. The south bearing tree, an 8" Fir bearing S 15W, 14 links, had fallen over and rotted but scribing was still visible. The point of a yew post was found, as described, from the bearing tree. The north bearing tree, an 8" white fir, bearing N 89 W, 17 links had completely disappeared.

The corner was marked with a 1" rod driven 18" into the ground. A 38" Douglas Fir, N 39 $\frac{1}{2}$ E, 14 feet, was referenced and scribed $\frac{1}{4}$ S 22, RS 424, BT. A 24" Douglas, S 18 $\frac{1}{2}$ W, 20.9 feet, was referenced and scribed $\frac{1}{4}$ S 27, RS 424, BT.

Bearing trees were referenced with a compass and chain. Magnetic declination used was 19 $\frac{1}{2}$ ^o E. This work was done September 18, 1959 by Wallace Owen and Tom Mehl III. Witnessed by Robert Harris and Lorne Swearingen.

Yours very truly,

THE ROBERT DOLLAR CO.

Wallace Owen

Wallace Owen
Registered Surveyor 424

WO/jvd

FILED
RECEIVED

SEP 28 1959

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 42/424²