

Have renewed the following corners.

North Cor. Sec. 1 & 2 T. 33 S. R. 6 W. found both O.B.T.

Drive 1" I.P. Scrib 14" Maple S. $10^{\circ}50'W$. 57.0

14" Fir N. $83^{\circ}20'E$. 78.8

Run West 201.4 ft. to Cor. 35 & 36 T. 32 S. R. 6 W.

Find both O.B.T. Drive 1" I.P.

Scrib 18" Fir N. $60^{\circ}33'E$. 65.8

24" Fir N. $33^{\circ}50'W$. 33.9

E of Hwy 99 (New) is 1025.0 ft. West of Cor. to

Sec. 1 & 2. All other corners on West to $\frac{1}{4}$ Cor.

of Sec. 4 T. 33 S. R. 6 W. are destroyed.

At South $\frac{1}{4}$ Cor Sec. 2
T. 33 S. R. 6 W. drive $\frac{3}{4}$ " pipe
over a $\frac{3}{8}$ " Iron Rod.

Respectfully,

Geo. J. Wenderoth
Deputy.

C. S. File No. 47/7