

June 14, 1956
R. Hamilton
J. Fee et al

Renew $\frac{1}{4}$ Cor bet $\frac{6}{5}$ T31SR2W

Fd. stake set in location of original Yew tree. Tree was knocked over during road const. Stake was set by Richard Hamilton to preserve location.

Cor. fell on cut Bank so set Wit Cor 25.0' South. Set Brass Cap Mkd. County Surveyors Office T31SR2W, Wit Cor $\frac{1}{4}$ S $\frac{5}{6}$, true Cor 25.0' North, 1956

From which:

16" W. Fir beam S 88° W 6.3 ft
Mkd $\frac{1}{4}$ S $\frac{5}{6}$ CS BT
14" W. Fir beam S 22° E 29.5 ft
Mkd $\frac{1}{4}$ S $\frac{5}{6}$ CS BT

Renew cor $\frac{6}{5}$ T31SR2W

Fd DIST, 28" Fir, blown over. Scribing visible. Fd Stump 40" Fir no scribing. Set Brass Cap Mkd County Surveyors Office $\frac{6}{5}$ 1956
 $\frac{7}{8}$

From which:

8" R. Fir beam S 19° W 3.4 ft
Mkd S $\frac{7}{8}$ CS BT
6" R. Fir beam N 28° W 23.3
Mkd S $\frac{6}{5}$ CS BT
No other trees near

DIETZEN NO. 385-6

#31

C. S. File No. 47/89