

R5W R4W

RENEW 1/4 COR 36 | 31
T303

FD. ORIG S 29° W 50.8' NOW 48"
FIR BT. ALIVE & GOOD CONDITION
I OPEN & FIND GOOD SCRIBING (1/4 S)
THE ORIG. 18" LAUREL N 90° E IS
ROTTED NO SCRIBING FD. BOTH BTS
CHECK FOR BEARING & DIST.

SET BRASS CAP AT COR MKD.
1/4 S 36 | 31 T303 COUNTY SURVEYORS
OFFICE 1957
R5W R4W

FROM WHICH 10" CEDAR BEAMS
S 60° E 19.4' SCRIBED 1/4 S 31 C S BT.

BARK SCRIBED ORIG. S 29° W 48"
FIR 50.8'. BT SCRIBED 1/4 S 36 C S BT
BARK SCRIBING JUST ABOVE OLD FACE

YAR 20 1/2

APRIL 11-57
J. B.
N. G.
J. H.

DIETZGEN NO. 3855-6

C. S. File No. 97/175