

C.C. SEC 34 T30SR4W
 SEC. 31
 T30S R5W SEC. 6
 T31SR4W

FOUND TREES TO NE & SE ALIVE
 & IN GOOD CONDITION SHOWING GOOD SCARS
 THE PINE TO THE SW HAS BEEN CUT
 BUT STUMP STILL IN PLACE. CHOPPED
 OUT PINE STUMP AND FOUND OLD FACE
 WITH TRACES OF SCRIBE MARKS. FACE IS
 CHARRED AND HAS EVIDENTLY BEEN BURNED
 DESTROYING MOST OF SCRIBE MARKS.
 AT INTERSECTION OF DISTANCES FROM
 B.T. & STUMP FOUND BEARINGS TO AGREE
 WITH GOV'T FIELD NOTES. SET 1" PIPE
 WITH BRASS CAP MARKED

COUNTY SURVEYORS
 C.C.
 T30S R5W SEC. 6
 T31SR4W
 S 36 1957
 OFFICE

MARK ONE NEW B.T.
 10" MADRONE N 50° W 21.2 FT
 SCRIBED T30SR5W S36 CS BT