

RENEW SEC COR. 31 32 R 7W

30 29 T 25 S

6" UNDER

FOUND - 1" I. PIPE AT COR AND
A B.T.S. AS RENEWED BY STEWART
1927

THE 10" MAPLE S 50° W & THE 10"
MAPLE NOW 18" N 38° W SHOW
GOOD HEALED BLAZES I DO NOT
DUBBY. THE 12" NOW 18" ALDER
SHOWS GOOD BUT PARTLY
ROTTED WORKING. THE NE BT
LOG 26" ROTTED STUMP.

SET BRASS CAP ALONGSIDE
1" I.P. MKD. 331 329 T 25 S R 7W
31 532

COUNTY SURVEYORS OFFICE 1957

NEW B.T.S.

14" R. FIR S 53° E 30.1'
AS B.T.S. T 25 S 32 R 7W

16" R. FIR N 28° E 66.8'
AS B.T.S. T 25 S 329 R 7W

SEPT. 10-57

W.B.
M.G.

VAR 20 1/2°

DIETZGEN NO. 385-6

C. S. File No. 49/10-1