

RENEW 1817 T 255 RTW
1920

FOUND - ROTTED SNAG ORIG BT
12" NOW 6" FIR N27°E 79' SCRIBE MKS
VISIBLE ALSO FND 18" FIR FACE ROTTED
TO SCRIBE MKS FOUND CHECKS BEARING
ADJUST FOR NW ORIG BT THE SE ORIG
BT OPEN TO OPEN ORIG. 12" NOW 16" FIR
S 24 1/2° W RECORD 50.2' I FND DIST
SHOULD BE 31.4' (CHECKS BEARING)
FIND SCRIBING "T"

SET BRASS CAP AT COR. MKS.
S 18 1/2° T 255 R 7W COUNTY
S 19 1/2° SURVEYORS OFFICE 1957.

NEW BTS.

16" R. FIR N28°W 69' SCRIBED S18
T 255 R 7W CS BT
50" R. FIR S 22 1/2° E 259' SCRIBED
S 20 T 255 R 7W CS BT. THIS BT
WAS OPENED ABOUT 15 YEARS AGO
I SCRIBE BELOW S 20 T 255 R 7W
CS BT
I RECKONED THE ORIG SW BT
18" R. FIR S 27°W 31.4' SCRIBED S19
T 255 R 7W CS BT
6" R. FIR EAST 579' SCRIBED S17
T 255 R 7W CS BT.

VAR. 20 1/2°

Nov. 6 - 1957
J. BYRON
S. BILLOW

DIETZGEN NO. 3895-6