

RENEW $\frac{1}{4}$ COR. 23/24 T 285 RW

FD 1" I. ROD IN N.S. FENCE LINE
BOTH B.T.S AS RECORDED BY BOYER
1936 ALIVE & IN GOOD CONDITION
THE SE BT NOT GROWN OVER
SCRIBING VISIBLE. THE SW BT
HAS BURNED FACE NO SCRIBING
VISIBLE I DESCRIBE THIS BT
 $\frac{1}{4}$ 23 AS BT. BOTH B.T.S
CHECK FOR BEARINGS & DIST

RENEW $\frac{1}{4}$ COR. 19 T 285 RW

FOUND - TWO SNAGS WHICH I BELIEVE
WERE THE ORIG B.T.S FOR $\frac{1}{4}$ COR.
THE SOUTH 24 S. NOW 22" FIR
SNAG SHOWS REAL OLD FACE AND
WHAT I BELIEVE TO BE SCRIBED MKS.
"H B" BT BARK SCRIBED.
THE N 25° W 6.6' LAUREL SNAG
SHOWS REAL OLD FACE CENTER
RETTED NO SCRIBED MKS FD. NOW
24"
B.T.S. CHECK FOR BEARINGS, DISTANCES

BRASS CAP AT COR MKD
 $\frac{1}{4}$ S $\frac{15}{30}$ T 285 RW COUNTY SURVEYORS
OFFICE 1957

NEW B.T.S.
12" FIR N 61° E 137' SCRIBED $\frac{1}{4}$ S
19 CS BT.

14" FIR S 62° E 200' SCRIBED $\frac{1}{4}$ S
30 CS BT

AUG 30-57

J.B.
M.G.