

SEARCH FOR 1131 T265 R3W
65 T275

FOUND — 3/4" FIR. AT CORNER AS RECORDED
BY ARE 1950. I ALSO FIND ORIG.
8" NOW 15" W. OF STUMP I OPEN NEAR
BASE & FIND GOOD SCRIBING. 1"
THIS BT CHECKS FOR ORIG. SIZE
APPARENT OVERGROWTH & FEELS OK
NO CHANCE TO MAKE A RING COUNT AS
STUMP IS PARTLY ROTTEN. I BELIEVE
BEYOND ANY DOUBT THAT THIS IS AN
ORIG. BT. THE ORIG. WERE BT'S
WOULD BE IN A OLD CULTIVATED
AREA I FIND NO TRACE OF EITHER
BT NOR SW BT.

I ALSO FIND ARE 30" 80. NOW
DOWN NAD W 65.0' SHOWS GOOD
SCRIBING. 20" FIR 232.00 30.9'
NOW LOW CUT STUMP NO SCRIBING NO.

~~BRASS CAP SET OCT 17 1958
H. D. CORBETT (ON YELLOW TAG) BEARS N61°W
31.7'~~

~~NOTE — THE SURVEYOR WHO SET
GOV. BRASS CAP USED ARE 1. BA. BT
FIR ORIG.~~

H. D. CORBETT

GOV'T BRASS CAP SET
OCT. 30, 1958 IN ABOVE POSITION.

NOTED
FOUND CORNER IN CORBOOK CS.FRE No 49/1410

DIETZEN NO. 385-B