

RENEW SEC. COR. $\frac{27}{318}$ T 283

FOUND - WIRE FENCE COR. FENCE TO
NORTH & FENCE TO EAST. I FIND 48" FIR
STUMP S 33° E 442 (RECORD DIST & BEARING)
SHOWS REAL OLD AXE MARKS. ALL OTHER
ORIG. BTS. GONE. I ALSO FIND $\frac{1}{2}$ " IRON
AT FENCE COR.

I WM. MELTON STATE THAT THE
48" STUMP USED ON THIS DATE TO FIX THE
POSITION OF THIS SEC. COR. IS ONE OF THE
ORIGINAL BTS. THAT I HAVE SEEN OTHER
BTS. FOR THIS CORNER WHICH HAVE BEEN
DESTROYED. THAT I WAS ^{FIRST} TO THIS SEC. COR.
ABOUT 50 YEARS AGO AND BEEN BACK
MANY TIMES SINCE. I SAW SCRIBE
MARKS ON THE ABOVE MENTIONED 48"
BT. BEFORE TREE WAS CUT.

SIGNED

OCT. 23 -57

Wm Melton

N 89° 46' 138.8 (F)

SET BRASS CAP AT SIDE OF $\frac{1}{2}$ " IRON
MKD. $\frac{12}{17}$ RAW T 283 COUNTY SURVEYORS
OFFICE 1957

NEW BTS.
14" MYRTLE BEARS S 18° W 46.7
SCRIBED S 13° T 283 IR 5 W
8" N. FIR BEARS N 84° W 138.8
SCRIBED S 12 C 5 BT

DIETZEN NO. 385-6