

RENEW 17/16 T 245 R 7W

FOUND - 1 1/2" AXE AT COR  
12" NOW 18" FIR N 80° W 23.5'  
B.T. NOW SNAG 5' NOW 12" W. OAK SHOWS  
GOOD JOINT DO NOT OPEN NEAR  
S.W. PTS CORNER

NEW BT  
26" W. OAK BEARS N 75° E 12.58'  
SCRIBED 3/6 T 245 R 7W C.S. BT

MARCH 25 - 60  
I. BYRON  
M. G.  
C.P.



RENEW 1/4 COR 31 T 245 R 7W  
6 T 255

FOUND - ORIG 18" NOW 26" B. OAK  
CENTER PARTLY ROTTED SHOWS  
GOOD SCRIBING (REVERSE) ORIG  
SOUTH W. CORNER

SET BRASS CAP AT COR. MKD  
COUNTY SURVEYORS OFFICE 1960  
1/4 31 T 245 R 7W  
56 T 255

NEW B.T.  
6" R. FIR BEARS S 35° E 9.4'  
SCRIBED 1/4 S B C.S. BT

5" R. FIR BEARS N 70° E 9.0'  
SCRIBED 1/4 31 C.S. BT



DIETZEN NO. 385-6

C. S. File No. 49/41-27

7-28-7

SEC. CAR

#57

$$\begin{array}{r} 17 \overline{) 16} \\ \underline{20} \phantom{0} \\ 21 \end{array}$$

BT - OAK N 5° E

Rec 12.58'

ACRUAL 125.8'

typical error

Insp. from  
Jury 4/6/76

M.M.

12-14/64-20