

RENEW $\frac{1}{4}$ COR. 6/5 T 295 R 710

FOUND - ORIG. 20" NEW 30" R. FIR
N 62° E 3.3' I OPEN & FIND GOOD
SCRIBING "BT" ORIG. NW BT NOW
DOWN & MOSTLY ROTTED CHECKS
BEARING & DIST. TO STUMP SECTION,
ALSO FIND $\frac{1}{2}$ " I.P. 10' SOUTH.

SET BRASS CAP AT CORNER
MND. COUNTY SURVEYORS OFFICE
1960 $\frac{1}{4}$ S 6 | S 5 T 295 R 710.

NEW BTS.

RESCRIBE NEW 30" R. FIR
N 62° E 4.0' $\frac{1}{4}$ S 5. CS BT.

8" W. FIR BEARS 54.8' W 9.3'
SCRIBED $\frac{1}{4}$ S 6 CS BT.

FILED

RECEIVED

SEP 0 1960

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

CS 49/41-40

*

✓