

RENEW  $\frac{1}{4}$  COR

35 T235 R5W  
2 T245 R5W

FOUND - 14" W. O. N 16' E 27' 8"  
SCRIBED BY TRAIL 1921 SHOWS  
GOOD SCRIBING  $\frac{1}{4}$ " I FIND STUMP  
HOLES ONLY FOR ORIG. BTS

I RALPH COCKERAM STATE  
THAT I WAS WITH TRAIL AT THIS  
CORNER 1921 WE FOUND BOTH ORIG.  
BTS. AND SOON ATERWARDS I SET  
THE EXISTING ANCHOR POST AT  
 $\frac{1}{4}$  COR. AS ESTABLISHED BY TRAIL  
Ralph Cockeram

SET BRASS CAP AT COR E ALONGSIDE  
ANCHOR POST. MKD. COUNTY SURVEYORS  
OFFICE 1959  $\frac{1}{4}$  S 35 T 235 R 5W  
J 2 T 245

NEW BTS.

7" R. F. R. BEARS S 2' E 19 0'  
SCRIBED  $\frac{1}{4}$  S 2 C 3 BT.

12" W. O. N S 26' W 19 4' (TRAIL)  
SHOWS GOOD MARKS I DO NOT OPEN

NOV. 27 - 59

J. B.  
M. G.  
C. P.

RALPH COCKERAM

✓✓✓

C. S. File No. 19/42

DIETZGEN NO. 3895-6

26