

REVIEW $\frac{21}{22}$
21/22

T 295 R 3 W

FOUND - ALL FOUR ORIG. BTB. ORIG.
36" NOW 44" FIR SNAG N 5° E 52.9'
SHOWS GOOD BARK SCRIBING, ORIG.
12" NOW 30" LAUREL S 10° W 29.0'
CEDAR ~~ROTTER~~ ORIG. 10" NOW 18"
FIR S 16° E 16.5' SHOWS GOOD SCAR I DO
NOT OPEN. ORIG. 6" NOW 18" FIR N 3° W
21.8' SHOWS GOOD SCAR I DO NOT OPEN.

GET BRASS CAP AT COR. MUD

521/522 T 295 R 3 W COUNTY SURVEYORS
528/527 OFFICE 1959.

NEW BTB.

20" R. FIR BEARS N 39° E 28.9'
SCRIBED 522 T 295 R 3 W COR

6" R. FIR BEARS S 60° W 56.1'
SCRIBED 528 COR

REVIEW $\frac{1}{4}$ COR $\frac{28}{33}$ T 295 R 3 W

FOUND - ORIG. 6" NOW 6" CEDAR SNAG
COR TREE SCRIBED $\frac{1}{4}$ S, $\frac{1}{4}$ S" ORIG.
WITH $\frac{1}{4}$ " PIPE AT BASE. ORIG.
15" NOW 32" FIR STUMP S 70° E 30.1'
SHOWS BARK SCRIBING FOLD SCARS A
STUMP HOLE CHECKS BEARING & DIST. FOR
ORIG. NW BT.

NEW BTB.

13" R. FIR BEARS S 32° W 27.5'
SCRIBED $\frac{1}{4}$ S 33 COR

12" R. FIR BEARS N 8° W 53.7'
SCRIBED $\frac{1}{4}$ S 28 COR

Feb 1959

C. S. File No. 49/47.1

DIETZEN NO. 388-5