

RENEW S $\frac{1}{4}$ S32 T23S R7W

FOUND - $\frac{3}{4}$ " I.P. AT COR & BT

AS RECORDED BY GRANT. ALSO
FIND BASE OF LARGE ROTTED FIR
STUMP THAT CHECKS ORIG. DIST. &
BEARING FOR S W BT.

NOTE - COR. PILE IS ALONGSIDE
F. EWEWOOD FENCE POST & IS SCRIBED
 $\frac{1}{4}$ S32.

RE-SCRIBE NEW BT.

10" W. OAK BEARS S32° W 292'
 $\frac{1}{4}$ S32 CS BT

* $\checkmark \checkmark \checkmark$
RENEW 32|33 - 23S R7W

FOUND - ORIG. 14" NOW 22" R. FIR
N45° W 25.1' SHOWS GOOD BARK
SCRIBING '3 T-23S R7W" ORIG.
22" NOW 38" R. FIR S75° E 356' SHOWS
GOOD BARK SCRIBING '54" ORIG.
BY NOW BY SPIKE STUMP OF ORIG. NE BT
ORIG. SW BT NOT FOUND.

SET BRASS CAP AT COR. MKD
COUNTY SURVEYORS OFFICE 1960

~~S32|S33~~ - 23S R7W
T-23S

NEW BTs.

10" CEDAR BEARS N 29° E 359'
SCRIBED S32 T-23S R7W CS BT

RE-SCRIBE NOW 22" R. FIR N45° W
25.1' S32 T-23S R7W CS BT

SECT. 8 - 60

J. D.

M. S.

C. P.

* $\checkmark \checkmark \checkmark$
C.S. File No. 49/49-8