

RENEW SOUTH  $\frac{1}{4}$  S 31 T 27 S R 6 W

FOUND - DUG 24" NOW 48" B. OAK  
S 73° E 137.9' WE OPEN & FIND  
GOOD SCRIBED MARKS "S" DRIB.  
16" NOW DOWN 40" OAK  
W. O. S. I. D. R.

WE ALSO FIND 1" I. PIPE AT  
COR. E. W. FENCE 15' SOUTH

BRASS CAP NOT SET

NEW BTS.

6" B. O. BEARS N 29° W 159'  
SCRIBED  $\frac{1}{4}$  S 31 S S B T.

8" W. O. BEARS N 26° E 107'  
SCRIBED  $\frac{1}{4}$  S 31 S S B T.

RENEW NORTH  $\frac{1}{4}$  S 6 T 28 S  
R 6 W

FOUND - DUG 12" NOW 26" W. OAK  
S 77° E 156.4' WE OPEN & FIND  
GOOD SCRIBING "S" DRIB. 24" NOW 48"  
B. OAK SNAG S 83° W 209.9' SHOWS  
SCAR.

NOTE: COR. UNDER E. W. FENCE

SET BRASS CAP AT COR. MND.  
COUNTY SURVEYORS OFFICE 1961  
NORTH  $\frac{1}{4}$  S 6 T 28 S R 6 W.

NEW BTS.

15" W. OAK BEARS S 73° E 42.5'  
SCRIBED  $\frac{1}{4}$  S 6 C S B T.

14" W. OAK BEARS S 55° W 358'  
SCRIBED  $\frac{1}{4}$  S 6 C S B T.

JAN. 23 - 61  
J. B.  
M. C.  
C. P.

DIETZGEN NO. 385-B

e.s. 49/59-32