

REVIEW T29SR6W $\frac{1}{4}$ S26
S35

AT COR. KD. 1" IRON PIPE

FD. WHITE OAK (NOW 18" DIAM.)
S $37\frac{1}{2}^{\circ}$ E 68⁰ FT. (TO FACE OF TREE.)
SHOWS GOOD SCAR.

FD. WHITE OAK (NOW 22" DIAM.)
N 28° E 66⁰ FT. (TO FACE OF TREE.)
SHOWS GOOD BARK SCRIBING " $\frac{1}{4}$ S26
CS BT" BLAZE & RESCRIBE THIS TREE.

AT COR. SET IRON PIPE WITH BRASS
CAP AND. "COUNTY SURVEYOR'S

OFFICE 1961 T29SR6W $\frac{1}{4}$ S26"
S35

DID NOT SCRIBE ANY NEW TREES.
BOTH OAK B.T.'S IN GOOD CONDITION.
NO TRACE OF FIR B.T. COULD BE
FOUND.

JUNE 15, 1961

J. B.
M. G.
C. P.

Mils & Godfrey

*

110

C. S. File No.

49/52