

RENEW SEC. COR. ^{28/27} 33/34 T 22 S R 5 W

FOUND - ORIG. 20" NOW 54" S 15° W 97 1/2
B. DAX NOW DOWN I OPEN & FIND GOOD
SCRIBING "B" 1" I ALSO FIND POSSIBLE
ORIG. SET BT CHECKS BEARING & DIST.
NOW 40" MAPLE ALIVE BUT ROTTED
INSIDE. NO SCRIBING FOUND. I FIND NO
TRACE OF ORIG. N.E. & S.W. BTS.

NOTE - COR. IN E.W. FENCE LINE.

SET BRASS CAP AT COR. MIKE COUNTY
SURVEYORS OFFICE 1958. T 22 S R 5 W

528/527
533/534

NEW BTS.

10" W.O. S 56° W 109 1/2'
SCRIBED 533 T 22 S R 5 W C&BT

24" MAPLE N 32° W 59 1/2'
SCRIBED 528 T 22 S R 5 W C&BT

89 1/2' E. OLD FAC. HCY BEARS EAST

DIETZEN NO. 3855-6

FILED
RECEIVED

MAR 6 1958

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

MAR 20 1958

MARCH 5-58
BYRON
S. B. L. O. V.

C.S. File No. 49/59 1/2