

RENEW $\frac{1}{4}$ COR. S 9 / S 10 T 22 S R 4 W

FOUND - ORIG. 12" NOW 36" CEDAR
N 58° E 12.5'

HAS GOOD REVERSE SCRIBING ON LARGE

CHIP CUT OUT 2 OR 3 YEARS AGO. I

FIND HOLE IN GROUND THAT CHECKS BEARING

& DIST FOR ORIG. S W BT.

SET BRASS CAP AT CORNER MWD

$\frac{1}{4}$ S 9 / S 10 T 22 S R 4 W COUNTY
SURVEYORS OFFICE 1958.

NEW B.T.S.

I RE-SCRIBE NOW 36" CEDAR

N 58° E 12.5' $\frac{1}{4}$ S 10 CS BT.

13" R. FIR S 41° W 47.1'

SCRIBED $\frac{1}{4}$ S 9 CS BT

MAY 1958

CS 49/59-23