

RENEW ⁴⁶ T 22 S

RSW RSW

FOUND - SCRIBED STAKE 1" AXLE AT
CORNER ORIG 20" NOW 40" DOWN & PARTLY
ROTTED PREVIOUSLY OPENED SHOWS GOOD
SCRIBING 111" S 10° E 429' ORIG. STAKE
NOW 44" SMALL OF ROTTED FIR S 68° W
350' SHOWS OLD SCARS. ORIG. 20" NOW 40"
DOWN & PARTLY ROTTED FIR N 68° W 422'
SHOWS OLD SCARS NO SCRIBING LEFT ORIG
30" NOW STUMP HOLE ONLY N 70° E 337'

SET BRASS CAP AT CORNER MKD
COUNTY SURVEYORS OFFICE 1879.

51 56 T 22 S
512 57

RSW RSW

THIS CORNER RENEWED SEVERAL
YEARS AGO BUT NOT RECORDED IN THE
SAME BTO. IN NE & SE. IT DESTROY
SCRIBING ON BTO TO NW & SW

NEW BTO.

20" CEDAR BEARS N 16° E 468'
SCRIBED T 22 S RSW 56 BT (I ADD 58)

18" CHINQUIN BEARS S 30° E 198'
SCRIBED T 22 S RSW 57 BT (I ADD 63)

6" R FIR BEARS N 64° W 130'
SCRIBED T 22 S RSW 51 CS BT

6" HEMLOCK BEARS S 77° W 308'
SCRIBED T 22 S RSW 512 CS BT

APRIL 22-59

VAR 20 1/2° J.B.
S.B.

✓ ✓ C. S. File No. 49/59 1/9

DIETZEN N O. 385-6