

3233 T 215
 RENEW $\frac{5}{4}$ T 225 RSW

FOUND -- 12" NOW 40" FIR N 42° E
 SHOWS GOOD SCAR I DO NOT
 OPEN REMAINS OF ROTTEN STUMP FD
 CHECKS BEARING & DIST FOR ORIG. NW
 BT. I FIND FIR SNAG PREVIOUSLY
 OPENED SHOWS GOOD SCRIBING S 50 1/2° W
 83.0 (CORR). I ALSO FIND CUES
 S 69 3/4° E 54.0 BT PREVIOUSLY
 OPENED. I FIND 1" I.P. AT CORNER
 DRIVEN IN 1 1/2" I.P. SET BY CORR

I DO NOT SET BRASS CAP AT COR

NEW BTS.
 9" R. FIR BEARS N 51° W 180'
 SCRIBED T 215 RSW S 32 CS BT
 8" R. FIR BEARS S 38 1/2° W 39.5'
 SCRIBED T 225 RSW S 5 CS BT

8" R. FIR BEARS S 20° E 310'
 SCRIBED T 215 RSW S 4 CS BT

VAR 2050 ✓ AUG 19-59
 J.B.
 M.G.
 C.D.

RENEW $\frac{1}{4}$ COR $\frac{32}{5}$ T 215 RSW

FD - NO ORIG. BTS. I DO FIND BOTH OF
 THESE BTS. 20" NOW MOSTLY ROTTED
 SINKING STUMP 2000 SCRIBING BT
 FD. S 110° E 29.7' 19" NOW 30" FIR
 STUMP CHECKS BEARING FOR NW BT
 SET BRASS CAP AT COR MIND COUNTY
 SURVEYORS OFFICE 1951 S 32 T 215 RSW
 NEW BTS.
 38" R. FIR BEARS N 7° E 194'
 SCRIBED $\frac{1}{4}$ S 32 CS BT

17" LAUREL BEARS S 54 1/2° E 443'
 SCRIBED $\frac{1}{2}$ S 5 CS BT

13" R. FIR BEARS S 71 1/2° E 70.3'
 SCRIBED $\frac{1}{4}$ S 5 CS BT

8/1959 ✓✓

C.S. File No. 49/59-32

DIETZGEN NO. 385-6