

REN

T 22 S R 5 W

 $\frac{1}{4}$  S 23  
S 26AT COR, FD. REINFORCING ROD,  $1\frac{1}{2}$ "DIAM. - STAMPED  $\frac{1}{4}$  S <sup>23</sup> 26 ON TOP.

FD. FIR STUMP (NOW 36" DIAM.)

S 42° W 30° FT. - (RECORD 29° FT.) -

SLIVER EXTENDING UP FROM NEAR CENTER  
OF STUMP SHOWS OLD SCRIBING "S" -

AT APPROX. 4" DIAM.

FD. FIR SLAB - (ONLY PORTION  
OF LARGE DOWN FIR REMAINING STANDING)  
- N 2° E 52° FT. - NO MKS. FD. -  
TREE PROBABLY BARK SCRIBED; & BARK  
HAS BEEN BURNED & IS FLAKING OFF  
BADLY.

DID NOT SET NEW COR. MONUMENT.

BLAZE &amp; SCRIBE NEW TREES:

11" DOUG. FIR N 30° W 21 $\frac{1}{2}$  FT.MKD. "  $\frac{1}{4}$  S 23 CS BT "21" DOUG. FIR S 3° E 89 $\frac{1}{2}$  FT.MKD. "  $\frac{1}{4}$  S 26 CS BT "

MAY 15, 1963

M.G.

V.T.

Mils E. Gregory

Pre-  
Removal #28

FX✓

C. S. File No. 49/59-38