

RENEWY $\frac{1}{4}$ S $\frac{24}{25}$ T23S R10W

#1" IRON PIPE

FOUND - 1" IRON ROD AT COR. CHECK

BEARING & DIST. TO FLEARS N58 $\frac{3}{4}$ 'W
36.9' BT WHICH SHOWS VISIBLE SCRIBE
MKS. FLEARS N32'E 61.0' BT
IS DOWN & IN CRK. SCRIBE MKS. VISIBLE

SET BRASS CAP AT CORNER

MK12, $\frac{1}{4}$ S $\frac{24}{25}$ T23S R10W
COUNTY SURVEYORS OFFICE 1957.

NEW BTS.

28" MYRTLE N58 $\frac{3}{4}$ 'W 37.8' (TO CTR
OF TREE) SCRIBED $\frac{1}{4}$ S 24 CS BT.

27" MYRTLE N2'W 58.0'
SCRIBED $\frac{1}{4}$ S 24 CS BT

FILED
RECEIVED

JAN 16 1958

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

CS 49/60-2

#29