

REN. T 23 S R 10 W COR. 27/26  
SECS. 34/35

AT COR. FD. BADLY ROTTED WOODEN

STAKE - SCRIBED. - Ren #19

FD. HEMLOCK (NOW 24" DIAM.)

S 51° W 31° FT. - SCRIBING VISIBLE ON  
OPEN FACE " 3 23 R 10 W " - FACE  
STARTING TO DECAY.

FD. DOUG. FIR (NOW 42" DIAM.)

N 8½° E 33° FT. - VERY PLAIN  
SCARS VISIBLE.

FD. RED CEDAR (NOW 27" DIAM.)

N 4° W (NOT N 23° W) 5° FT. - SCRIBING  
VISIBLE IN NOT COMPLETELY COVERED  
SCAR.

AT COR. SET IRON PIPE WITH  
BRASS CAP MKD. "CS 1964 23-10  
27/26"  
34/35

BLAZE & SCRIBE 2 NEW TREES!

24" RED CEDAR S 10° E 22½ FT.

MKD. "T 23 S R 10 W S 35 CS BT"

24" HEMLOCK S 37° W 33½ FT.

MKD. "T 23 S R 10 W S 34 CS BT"

COR. LIES ON VERY STEEP N.W.  
SLOPE APPROX. 300 FT. SOUTH OF CREEK.

SEE REN #19

MAY 28, 1964

+ \* 10 ✓

Paul E. Godfrey

M.G.  
W.S.  
M.P.  
MS 4/9/60

Section 35 Twp 23S Rge 10 N Date: 4-20-64

How was corner identified? by bearing from road

Condition of corner:

mill creek county road to where road  
best route to reach corner: Clinch's toward the Impqua - Coon  
divide. The north line of S35 is first large clear cut. The  
1964 Lower Impqua tree planting is the clearcut 160 Ac  
spur road is discernible for 1/2 mile to N5 E of section 26.

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Karl F. Remond  
OLM Coon Bay

